

AD-A078 869

GANNETT FLEMING CORDRY AND CARPENTER INC HARRISBURG PA F/8 13/13  
NATIONAL DAM INSPECTION PROGRAM. BRYANT POND DAM (NDI I.D. NUMB--ETC(U)  
JUL 79 F FUTCHKO


DACW31-79-C-0015

NL

UNCLASSIFIED

1 OF 2  
AD  
A078869





MICROCOPY RESOLUTION TEST CHART  
NATIONAL BUREAU OF STANDARDS-1963-A



AD A078869

LEVEL

Distribution Unlimited  
Approved for Public Release  
Contract No. DACW31-79-C-0015

## **DISCLAIMER NOTICE**

1  
**THIS DOCUMENT IS BEST QUALITY  
PRACTICABLE. THE COPY FURNISHED  
TO DDC CONTAINED A SIGNIFICANT  
NUMBER OF PAGES WHICH DO NOT  
REPRODUCE LEGIBLY.**

⑥ National Dam Inspection Program.  
Bryant Pond Dam

SUSQUEHANNA RIVER BASIN,  
HARVEYS CREEK, LUZERNE COUNTY  
PENNSYLVANIA.

Phase I Inspection  
Report,

BRYANT POND DAM

NDI ~~to~~ Number PA-00544  
DER ID Number 40-11

ESTATE OF GLENDORA BRYANT

PHASE I INSPECTION REPORT

NATIONAL DAM INSPECTION PROGRAM

⑩ Frederick / Futchko  
Prepared by


GANNETT FLEMING CORDDRY AND CARPENTER, INC.  
Consulting Engineers  
P.O. Box 1963  
Harrisburg, Pennsylvania 17105

For

DEPARTMENT OF THE ARMY  
Baltimore District, Corps of Engineers  
Baltimore, Maryland 21203

⑪ JUL 1979

⑮ DACW31-79-C-0015



411 004

LB

## PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through frequent inspections can unsafe conditions be detected and only through continued care and maintenance can these conditions be prevented or corrected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the spillway design flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. The spillway design flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

Accession For	
NTIS	GNARI
DOC	TAB
Unannounced	
Justification	
By _____	
Distribution/	
Availability Codes	
Dist	Availand/or special
A	23



SUSQUEHANNA RIVER BASIN  
HARVEYS CREEK, LUZERNE COUNTY  
PENNSYLVANIA

BRYANT POND DAM

NDI ID No. PA-00544  
DER ID No. 40-11

ESTATE OF GLENDORA BRYANT  
PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM

JULY 1979

CONTENTS

	<u>Description</u>	<u>Page</u>
SECTION 1	- Project Information . . . . .	1
SECTION 2	- Engineering Data . . . . .	11
SECTION 3	- Visual Inspection . . . . .	13
SECTION 4	- Operational Procedures . . . . .	16
SECTION 5	- Hydrology and Hydraulics. . . . .	17
SECTION 6	- Structural Stability . . . . .	20
SECTION 7	- Assessment, Recommendations and Proposed Remedial Measures . . . . .	23

## PLATES

<u>Plate</u>	<u>Title</u>
1	Location Map.
2	Plan and Profile.
3	Section.
4	Spillway Profile.
5	Conditions in January 1975.

## APPENDICES

<u>Appendix</u>	<u>Title</u>
A	Checklist - Engineering Data.
B	Checklist - Visual Inspection.
C	Hydrology and Hydraulics.
D	Photographs.
E	Geology.

PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM

BRIEF ASSESSMENT OF GENERAL CONDITION  
AND  
RECOMMENDED ACTION

Name of Dam: Bryant Pond  
NDI ID No. PA-00544/DER ID No. 40-11

Owner: Estate of Glendora Bryant

State Located: Pennsylvania

County Located: Luzerne

Stream: Harveys Creek

Date of Inspection: 11 June 1979

Inspection Team: Gannett Fleming Corddry and  
Carpenter, Inc.  
Consulting Engineers  
P.O. Box 1963  
Harrisburg, Pennsylvania 17105

Based on visual inspection, available records, calculations, and past operational performance, Bryant Pond Dam is in very poor condition and is judged to be unsafe, emergency. With existing conditions, the spillway will pass only 2 percent of the PMF without overtopping the dam. A failure of the dam will increase the hazard to loss of life at one recently constructed home downstream. The spillway capacity is rated as seriously inadequate. The embankment has been overtopped twice in its operational history.

Furthermore, excessive settlement has occurred on the embankment, especially on the downstream rockfill, over its entire operational history. This has contributed to the breaking of the concrete core-wall. At present, the core-wall is broken and tilted over the entire length of the dam, except where the dam was breached and subsequently repaired. As the core-wall cannot be relied upon to be effective, the embankment is considered to be beyond repair.

The attempted repairs by the Owner were not designed or made in accordance with good engineering practice and are inadequate. The repairs to the breach area are unsafe.

The outlet works is considered to be beyond repair. There is no means of drawing down the reservoir.

Representatives of the Corps of Engineers visited the damsite on 14 June, 1979. A telegram was sent to the Governor of the Commonwealth on 19 June, 1979 informing him of the unsafe conditions at the dam and recommending that the dam be breached.

The following measure is recommended to be undertaken by the Owner immediately:

(1) Draw down the reservoir and then breach the dam. The breach should be of sufficient size that it is not possible to impound any significant quantity of water behind the dam during a flood. The method of breaching should be in accordance with good engineering practice. The breaching should be performed under the supervision of a professional engineer and it should be carefully accomplished by an experienced contractor to avoid creating a hazard downstream. Any structure that might replace the existing dam should be



considered a new structure by the Commonwealth. Due consideration of the poor performance history of the existing features of the dam should be given before an attempt is made to incorporate them into a new structure.

Submitted by:



GANNETT FLEMING CORDDRY  
AND CARPENTER, INC.

*Frederick Futchko*

Frederick Futchko  
Project Manager, Dam Section

Date: 7 August 1979

Approved by:


DEPARTMENT OF THE ARMY  
BALTIMORE DISTRICT, CORPS OF  
ENGINEERS

*James W. Peck*

JAMES W. PECK  
Colonel, Corps of Engineers  
District Engineer

DATE: 23 August 1979

BRYANT POND DAM



Overview

SUSQUEHANNA RIVER BASIN  
HARVEYS CREEK, LUZERNE COUNTY  
PENNSYLVANIA

BRYANT POND DAM

NDI ID No. PA-00544  
DER ID No. 40-11

ESTATE OF GLENDORA BRYANT  
PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM

JULY 1979

SECTION 1

PROJECT INFORMATION

1.1 General.

a. Authority. The Dam Inspection Act, Public Law 92-367, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a program of inspection of dams throughout the United States.

b. Purpose. The purpose of the inspection is to determine if the dam constitutes a hazard to human life or property.

1.2 Description of Project.

a. Dam and Appurtenances. Bryant Pond Dam is an earthfill and rockfill dam with a concrete core-wall. The earthfill extends along the upstream side of the core-wall and the rockfill extends along the downstream side. The dam, including the main and auxiliary spillways, is

CONT →



425

→ 425 feet long. The design height is 19 feet. The main spillway is located near the left abutment of the dam. It is a series of concrete slabs forming a cascade to the natural stream. Other than its exterior lines and grades, details of the main spillway are unknown. The main spillway crest is 40 feet long and 5 feet below the design top of the dam. The auxiliary spillway was designed to be a 175-foot long by 2-foot deep notch in the concrete core-wall. It was constructed 200 feet long. The auxiliary spillway was designed to allow water to flow over the rockfill on the downstream slope of the embankment. The outlet works is located directly to the right of the main spillway. It consists of two 2-foot square concrete conduits with concrete sluice gates at the upstream end. The various features of the dam, as designed, are shown on the Plates at the end of the report. The existing features are shown on the Photographs in Appendix D. ACOSTROT

b. Location. The dam is located on Harveys Creek, approximately 8.8 miles northwest of West Nanticoke, Pennsylvania. Bryant Pond Dam is shown on USGS Quadrangle, Harveys Lake, Pennsylvania, with coordinates N41°19'00" and W76°04'15" in Luzerne County, Pennsylvania. Harveys Lake is located upstream from Bryant Pond Dam on Harveys Creek 2.8 miles northeast of Bryant Pond Dam. A location map is shown on Plate 1.

c. Size Classification. Small (16 feet high, 120 acre-feet, existing conditions).

d. Hazard Classification. High hazard. Downstream conditions indicate that a high hazard classification is warranted for Bryant Pond Dam (Paragraph 5.1c.(5)).

e. Ownership. Estate of Glendora Bryant, care of Mr. Burt Bryant, R.D. 2, Dallas, Pennsylvania.

f. Purpose of Dam. Recreation.

g. Design and Construction History. Charles S. Miles, consulting engineer of Wilkes-Barre, designed Bryant Pond Dam in 1913. Construction of Bryant Pond Dam probably commenced in 1913 or 1914. There was an old timber crib dam at the site before this date. The dam was being constructed by Andrew Raub, executor of the Samuel Raub Estate, who was the original owner. The dam was originally

intended for recreation. Construction was started without the knowledge of the Pennsylvania Water Supply Commission (PWSC), who was legally responsible for issuing a permit prior to construction. The PWSC, upon discovering that the dam was being constructed, issued an order, in June 1914, to stop construction until plans for the dam were submitted and approved. The partially constructed dam was inspected by the PWSC in early July 1914. They discovered that the dam as constructed varied significantly from the design. They ordered that the Owner submit plans showing how the dam was constructed to that date and the proposed plans to complete the structure.

Revised plans were submitted to the PWSC in late July 1914, and a permit was issued dependant upon the removal of certain poor construction conditions incorporated into the original construction. The dam was inspected by the PWSC in September, November, and December 1914. Both the PWSC inspection reports and a letter from Mr. Miles indicate that the requirements of the PWSC had been met, except that the core-wall near the right abutment was constructed 1-foot below design elevation. The PWSC ordered remedial measures for the area. Specifics concerning the construction are addressed in Section 2.

In the first post-construction inspection by the PWSC during 1919, deterioration of the structure was noted. Repairs were ordered. Repairs were again ordered after the inspection of 1920. These were apparently never accomplished. Specifics concerning the inspection reports referenced hereafter are in Appendix A.

Bryant and Williams, an ice company, acquired the dam sometime between 1920 and 1922. Repairs were again ordered after the next PWSC inspection in 1922. In the PWSC inspection of 1923, it was noted that only some minor repairs had been accomplished. Further deterioration was noted in the inspections of 1924 and 1926, when repairs were again ordered. Repairs were again ordered in 1928. An inspection by the Commonwealth in 1929 noted that some repairs had been made but that the dam was still in poor condition. Additional repairs were ordered. Although some further repairs were accomplished, the Commonwealth threatened legal action in 1931 if all the required repairs were not made. The Owner accomplished further repairs in

1932 and 1933. The dam was overtopped in 1933 for a depth of 0.5 foot; it was reported that no damage was done to the embankment. Although some additional work was done in 1934, much additional remedial work remained.

Repairs were again ordered in 1936; these included the removal of flashboards that had been placed on the main spillway crest. In a 1938 inspection by the Commonwealth, it was noted that the flashboards had been removed, that two ice chutes had been constructed along the top of the dam, but that other repairs had not been made. The Owner stated at this time that he could not entail further expense for repairs.

The Commonwealth dropped the matter until 1952, when the Pennsylvania Fish Commission (PFC) took interest in the structure. The Commonwealth, in conjunction with the PFC, inspected the dam. Although it was "in a state of complete disrepair", with numerous defects, it was the Commonwealth's opinion that it would "last another 10 years". The Commonwealth informed the PFC in 1952 that the dam would have to be rebuilt, but that rebuilding or extensive repairs would not be required in the immediate future. The Commonwealth informed the PFC that work to be undertaken immediately in order to protect the structure for the immediate future included:

- "1. Remove all brush, trees, etc. from the embankment and for at least ten feet below the dam.
2. Remove enough of the present concrete core wall to secure a level crest throughout its length. This will cause overtopping to occur as a relatively thin sheet over the entire crest length and prohibit concentrations of flow at a few spots.
3. Additional heavy stone riprap will probably be necessary on the downstream face to provide an adequate fill to support the badly cracked core wall.
4. It may be necessary to place some thoroughly compacted clay fill on the upstream face in the area of the spillway to cut off excessive leakage at that point."

The PFC leased the dam about this time.



There was a misunderstanding about the terms of the lease. The Owner thought that the PFC would repair the dam. He wrote to the Commonwealth in 1971, complaining about its condition, which he claimed was hazardous. The Commonwealth responded to the Owner that, although it was in poor condition, it was not in imminent danger of failure. In January 1972, the PFC confirmed this opinion in a letter to the Commonwealth. In February 1972, the Commonwealth asked the PFC if they intended to maintain a dam at the site; the Commonwealth stated that the dam was in poor condition and that "it is our open question whether the existing dam should be rehabilitated or removed". The PFC responded that they were trying to settle the terms of the lease with the Owner.

The Owner reported that, two days prior to the peak flow from Tropical Storm Agnes in June 1972, a dam upstream failed, causing the overtopping of Bryant Pond Dam and the breaching of the embankment. The PFC terminated their lease shortly after this. Apparently, nothing immediately was done to repair the embankment. The Owner engaged an engineer to determine the feasibility of repairing the embankment. The engineer, Sweinberg and Kolesar Associates, of Forty Fort, surveyed the embankment in January 1975 (Plate 5).

Tropical Storm Eloise in September 1975, caused a substantial flow through the already breached dam. In October 1975, the Commonwealth met with the Owner and inspected the dam. The Owner stated that he wanted someone to repair it. The Commonwealth stated that the Owner would have to fund the repairs himself. The Owner tried to obtain funds from the Small Business Administration (SBA). Their loan was dependant upon approval by the Commonwealth of plans to repair the dam.

Plans were submitted to the Commonwealth in January 1976. The plans were prepared by Sweinberg and Kolesar Associates. The plans show a completely new structure, with the portion of the existing dam to remain to be determined by the Commonwealth. As such these plans are not relevant to this report.

The Owner discussed his intentions with the Commonwealth in April 1976. Previously, the Commonwealth had indicated that the plans were unsatisfactory because

they did not involve an analysis of the existing structure. Apparently the Owner then proposed to place large boulders "against the downstream face of the dam". The Commonwealth indicated that they would approve this, although they still would consider the dam to be in an unsatisfactory condition.

The Owner acquired some funds from the SBA. He used these to repair the dam to its present condition. Since 1975, a dwelling has been constructed about one-half mile downstream from the dam in the floodplain.

h. Normal Operational Procedure. The pool is maintained at spillway crest with excess inflow discharged over the spillway.

1.3 Pertinent Data.



Existing Conditions

Design Conditions  
(As constructed, may vary from design)  
13.7 of which 7.3 is controlled by Harveys Lake. (From Records).

a. Drainage Area. (square miles)

14.2 of which 6.6 is controlled by Harveys Lake.

b. Discharge at Damsite. (cfs.)

Maximum known flood at damsite  
Outlet works at maximum pool elevation  
Main spillway capacity at maximum pool elevation  
Auxiliary spillway capacity at maximum pool elevation  
Total spillway capacity at maximum pool elevation

Unknown  
Not Available

Unknown  
0

285

Does not exist

285

c. Elevation. (feet above msl.)

Top of Dam  
Maximum Pool  
Normal Pool (main spillway crest)  
Upstream invert outlet works  
Downstream invert outlet works  
Streambed at toe of dam (approximate)

1110.2  
1110.2  
1105.2

1106.7  
1106.7  
1104.7

Not Available  
1094.9  
1090.9

Not Available  
1094.9  
1090.9

<u>Reservoir Length. (miles)</u>		<u>Design Conditions</u>	<u>Existing Conditions</u>
d.	Normal Pool	0.38	0.38
	Maximum Pool	0.52	0.44
e.	<u>Storage. (acre-feet)</u>		
	Normal Pool	90	83
	Maximum Pool	193	120
f.	<u>Reservoir Surface. (acres.)</u>		
	Normal Pool	18	18
	Maximum Pool	22	19
g.	<u>Dam</u>		
	<u>Type</u>	Rockfill and earthfill with concrete core-wall.	Rockfill and earthfill with concrete core-wall.
	<u>Length (feet)</u>	425	425
	<u>Height (feet)</u>	19	16
	<u>Topwidth (feet)</u>	9	Varies 6 to 17

Existing Conditions

Design Conditions

g. Dam. (Cont'd.)

Side Slopes

Upstream

1V on 2H

Uncertain, vertical at areas near top.

Downstream

1V on 1.5H

Varies, vertical to 1V on 3.4H

Zoning

Core-wall

Core-wall (cracked)

Cutoff

Core-wall founded in trench.

Core-wall founded in trench.

1  
1

Grout Curtain

None

None

h. Diversion and Regulating Tunnel.

i. Spillway.

Main Spillway

Type

Broad-crested weir

Broad-crested weir

Length of Weir (feet)

40

40

Crest Elevation

1105.2

1104.7

Existing Conditions

Design Conditions

i. Spillway. (Cont'd.)

Upstream Channel

Reservoir

Downstream Channel

Cascade to natural stream

Auxiliary Spillway

Type

Broad-crested weir

Does not exist

Length of Weir (feet)

175

N/A

Crest Elevation

1108.2

N/A

Upstream Channel

Reservoir

N/A

Downstream Channel

Over rockfill on downstream slope of dam.

N/A

j. Regulating Outlets.

Type

Two 2-foot square concrete conduits.

Two 2-foot square concrete conduits.

Length (feet)

71

71

Closure

Concrete sluice gates at upstream end.

Permanently plugged.

Access

Bridge from top of embankment to operator.

None



## SECTION 2

### ENGINEERING DATA

#### 2.1 Design.

a. Data Available. Very little engineering data were available for review for the structure as originally designed or as modified during construction. In a study performed in 1914 by the Pennsylvania Water Supply Commission, an account of design concepts, geology, construction materials and methods, and design features was prepared for the components of the dam from interviews with the Owner, visual inspection, and other sources. The 1914 study also included analyses for hydrology and hydraulics. A summary of the results of the analyses is on file.

b. Design Features. The project is described in Paragraph 1.2a. The various design features of the dam are shown on the Plates at the end of the Report. The existing features are shown on the Photographs in Appendix D. A plan and profile of the dam, as designed, are shown on Plate 2. During construction, the auxiliary spillway shown on this plate was lengthened to 200 feet. Also, 2 chutes have since been added across the top of the dam (Photograph D). A typical section of the dam as designed is shown on Plate 3. A profile of the spillway is shown on Plate 4.

c. Design Considerations. The core-wall is unreinforced and relatively thin. It is shown as being 2 feet thick on Plate 3. The 1914 Pennsylvania Water Supply Commission Report states that the trench in which the core-wall is founded is 4 to 6 feet deep. The trench caved in during construction and the trench was re-excavated and filled with concrete to a thickness of 3 to 4 feet. The core-wall was carried up for a height of 8 feet with a design thickness of 2 feet, at which point the wall was battered to a thickness of 1 foot at its top. It is not certain the wall was designed to carry the anticipated loads.

#### 2.2 Construction.

a. Data Available. Construction data for the original structure that are available for review consist of the information contained in the 1914 report prepared by the Pennsylvania Water Supply Commission. The Pennsylvania Water Supply Commission's first report, of the dam as partially constructed, stated:

"No care has been taken to make an impervious embankment. The surface of the ground has not been stripped, and the logs of the old timber crib have not been entirely removed; the old creek channel has been filled with rock from the upstream toe to the core wall; the earth has been brought to the dam in scrapers and dumped in a loose fill, no attempt being made to deposit it in layers, or to pick out the stone, and the only means of compacting it was the travel over it."

As noted in Paragraph 1.2g, the Pennsylvania Water Supply Commission ordered changes to be made. In particular, it ordered future earthfill to be placed in layers and compacted, the logs of the old timber dam removed, and the stones in the creek bed removed.

The records state that these orders were complied with. It should be noted that the partially-constructed uncompacted embankment on an unstripped foundation was allowed to remain. Furthermore, the records state that no attempt was made to compact the rockfill on the downstream side of the core-wall.

b. Construction Considerations. It appears that initially the dam was poorly constructed. This may explain its poor performance history.

2.3 Operation. There are no formal records of operation. The records in the PennDER files indicate the embankment has performed poorly.

#### 2.4 Evaluation.

a. Availability. Engineering data were provided by the Bureau of Dam Safety, Obstructions, and Storm Water Management, Department of Environmental Resources, Commonwealth of Pennsylvania. The Owner made himself available for information during the day of the inspection.

b. Adequacy. The type and amount of design data and other engineering data are limited, and the assessment must be based on the combination of available data, visual inspection, performance history, hydrologic assumptions, and hydraulic assumptions.

c. Validity. There is no reason to question the validity of the available data. Some of the data is in conflict, but the conflicts are relatively minor.

SECTION 3  
VISUAL INSPECTION

3.1 Findings.

a. General. The overall appearance of the dam is very poor. Deficiencies were observed as noted below. A sketch of the dam with the location of deficiencies is presented in Appendix B on Plate B-1. Survey information acquired for this report is summarized in Appendix B. On the day of the inspection, the pool was 0.6 foot above spillway crest. The design main spillway is termed the spillway hereafter.

b. Embankment. The embankment is in very poor condition. Thick brush is growing along 50 percent of the upstream slope and at the right abutment of the downstream slope. The upstream slope in the 60-foot long reach that was breached during Tropical Storm Agnes is vertical with evidence of a minor amount of erosion. The top width in this breached area is 6 feet. The Owner reported that this area was repaired after Tropical Storm Eloise, but that he had insufficient funds to complete the repairs. Therefore, the downstream slope of the repaired breach section has been left vertical for 4 to 5 feet. At the bottom of the vertical drop, rockfill extends to the toe of the slope. At the top of the dam in the breach area, a 1-foot by 2-foot by 6-inch deep depression was observed.

The top of the core-wall is visible along the top of the dam, except in the breach area. It tilts about 45° downstream along the entire top of the dam except in the breach area, where it has been washed away, and in certain other areas, where it has broken off and is lying on the downstream slope. The top of the earthfill on the upstream side of the core-wall is uneven. It is a maximum of 1.6 feet below its design elevation except adjacent to the spillway, where it is 2.7 feet below its design elevation. The top of the core-wall, except at the breach area, is a maximum of 2.3 feet below its design elevation. The existing profiles are shown in Appendix B.



The rockfill on the downstream side of the core-wall is very uneven. Beneath one of the ice chutes it is washed out. The rockfill is covered with large, broken pieces of concrete. Some of these are part of the core-wall. The Owner reported that others are the remains of an old ice house that he used in lieu of rockfill to repair the embankment. Seepage was observed downstream from the embankment. Directly at the toe of the embankment a seep estimated at 1 gpm was flowing from a 200 square foot wet area. About 50 feet downstream the seepage increased to about 10 gpm at a localized area. This seepage then flowed to the creek. At the creek, the total seepage was estimated at 20 gpm. As a result of the previous overtoppings, the entire area downstream from the dam is covered with sediment and debris. Additional seepage was observed near the outlet works, as described hereafter.

c. Appurtenant Structures. The spillway is in fair condition. As water was flowing over it, a detailed visual inspection was not possible. It was noted that the downstream edges of the cascades were jagged and eroded. Cracks were observed in the cascade slabs. The spillway walls along the cascade are low. The top of wall is 0.6 foot above the cascade at one point. The area to the left of the left spillway wall is rockfill covered with poorly placed concrete. At the downstream toe of this area, seepage estimated at 10 gpm, including a localized seep of 5 gpm, was observed. The core-wall to the left of the spillway is intact. Cracks, which extend entirely through the structure, were observed at 4 locations. The wall is tilted forward near its center; it is also bowed.

There was no evidence of an auxiliary spillway. It apparently was washed out or it was indiscernable from the remainder of the core-wall.

The outlet works is in very poor condition. The remains of the gate operator were observed immediately upstream of the spillway. At the downstream end, a flow of about 1 cfs was discharging from the right conduit. No flow was visible from the left conduit. Although the conduits were reportedly constructed of concrete, they appear to be dry masonry covered with concrete. It is possible to see daylight through the left side of the left conduit. Seepage estimated at 20 gpm was observed



immediately downstream from the conduits. The Owner reported that an attempt had been previously made to plug the conduits with concrete and soil. He stated that the attempt was not entirely successful.

d. Reservoir Area. Harveys Lake, which controls about 50 percent of the drainage area, was visited on the day of the inspection. Harveys Lake watershed mostly consists of wooded rolling hills and the lake itself. Conditions at the outlet to the lake are sketched in Appendix C. The uncontrolled drainage area, which is below the Harveys Lake drainage area, is mostly wooded with rolling hills. Some of it is swampy. The remains of the dam upstream of Bryant Pond, which failed at the start of Tropical Storm Agnes, were observed. Development in the uncontrolled drainage area is minor. About 3 families live along the shore of Bryant Pond.

e. Downstream Conditions. Immediately downstream from Bryant Pond Dam is a small bridge that provides access for the families who live to the left of the damsite. About 0.5 mile downstream is one dwelling built on the fringes of the floodplain. The dwelling appeared to be of recent construction. Four persons were observed at the dwelling on the day of the inspection. About 300 feet downstream from the dwelling is a 12-foot high roadway embankment with four 6-foot diameter corrugated metal culverts. About 4 miles downstream from the roadway is Harveys Creek Canal Diversion Structure, which is owned by Pennsylvania Gas and Water Company and which is used for water supply. At the upstream end of the reach between the roadway embankment and the diversion structure, there are a few dwellings about 15 to 20 feet above streambed. The remainder of the reach is wooded and uninhabited. Access to Bryant Pond Dam is from a public road near the right side of the dam via a short unpaved private road.

## SECTION 4

### OPERATIONAL PROCEDURES

4.1 Procedure. The reservoir is maintained at spillway crest, Elevation 1104.7, with excess inflow discharging over the spillway and into Harveys Creek. The emergency drawdown outlet works is inoperable.

4.2 Maintenance of Dam. The dam is visited very frequently by the Owner. Informal inspections of the dam are made by the Owner. Formal inspections are not made. Brush is cut at irregular intervals. As described in Paragraph 1.2g, the many repairs ordered for this dam have essentially not been made. The repairs that have been made do not follow good engineering practice.

4.3 Maintenance of Operating Facilities. The operating facilities are not operable.

4.4 Warning Systems in Effect. The Owner stated that there is no emergency operation and warning system.

4.5 Evaluation of Operational Adequacy. The maintenance of the embankment and spillway is very poor. The outlet works is not operational nor could it be made operational. Inspections are necessary to detect hazardous conditions at the dam. An emergency operation and warning system is necessary to mitigate the hazards downstream, should stress become evident at the dam. Judging by the records in the PennDER files, the Owner does not have the resources to maintain and repair the structure.

## SECTION 5

### HYDROLOGY AND HYDRAULICS

#### 5.1 Evaluation of Features.

a. Design Data. The Pennsylvania Water Supply Commission prepared a report upon the application of the Owner, prior to issuing a permit for the continued construction of the dam. In that report, they estimated the design spillway capacity to be greater than 1,790 cfs. This was the combined capacity of both spillways. As noted in Section 3, the auxiliary spillway no longer exists.

For the existing spillway located near the left abutment, a discharge capacity of 285 cfs was used for this study. The existing spillway capacity was estimated including the effects of the low top of the dam (Appendix C).

b. Experience Data. The dam was overtopped in 1933 by 6 inches. No damage was reported from this overtopping. It was overtopped and breached during Tropical Storm Agnes in June 1972, apparently because of an upstream dam failure. The breach was not repaired when the dam was again overtopped by Tropical Storm Eloise in September 1975. It is not possible to estimate the flow for these overtoppings because the then existing top of dam profile is uncertain.

#### c. Visual Observations.

(1) General. The visual inspection of Bryant Pond Dam which is described in Section 3, resulted in a number of observations relevant to hydrology and hydraulics. These observations are evaluated herein for the various features.

(2) Embankment. The low areas along the top of the embankment reduce the spillway capacity. Other observations concerning the embankment are in Section 6.

(3) Appurtenant Structures. These features are evaluated in Section 6.



(4) Reservoir Area. No conditions were observed in the reservoir area that might present significant hazard to the dam. On the day of the inspection, a visit was made to Harveys Lake Dam. There is a roadway and culvert immediately downstream from the dam (Photograph J). It appeared that the roadway and culvert would be the control for all but low flows. This is confirmed by the analysis in Appendix C.

The breached dam observed upstream from Bryant Pond Dam confirms the Owner's statement of a upstream dam failure. However, judging by the size of the upstream dam, substantial additional inflow to Bryant Pond must have been occurring for the upstream dam to overtop Bryant Pond Dam.

The assessment of the dam is based on existing conditions. The effects of future development are not considered.

(5) Downstream Conditions. No conditions that would present a hazard to the dam were observed downstream. Although the recently constructed dwelling is at the fringes of the floodplain, the roadway immediately downstream of it makes its probability of being flooded high, were a failure of Bryant Pond Dam to occur. The other dwellings near the creek are sufficiently high that, although property damage might occur, the probability of loss of life is low. Harveys Creek Diversion Structure might sustain minimal damage from a failure of Bryant Pond Dam. Because of the number of persons observed at the recently constructed dwelling on the day of the inspection, a high hazard classification is warranted for Bryant Pond Dam. Access to Bryant Pond Dam is good.

d. Overtopping Potential.

(1) Spillway Design Flood. According to the criteria established by the Office of the Chief of Engineers (OCE), the Spillway Design Flood (SDF) for the size (Small) and hazard potential (High) of Bryant Pond Dam varies between the Probable Maximum Flood (PMF) and the 1/2 PMF. Because of the small downstream population, the 1/2 PMF is selected as the SDF.

(2) Description of Model. The watershed was modelled with the HEC-1DB computer program. The HEC-1DB computer program computes a PMF runoff hydrograph and routes the flows through both reservoirs and stream sections. In addition, it has the capability to simulate an overtopping dam failure.

The PMF inflow component to Harveys Lake Dam was computed and routed through the dam. The outflow was routed downstream and combined with the uncontrolled PMF inflow component to Bryant Pond Dam. The combined flow was routed through Bryant Pond Dam. Identical methods were used for various percentages of the PMF.

(3) Summary of Results. Pertinent results are tabularized at the end of Appendix C. The analysis reveals that the existing Bryant Pond Dam can pass 2 percent of the PMF without overtopping. It is estimated that, with its design conditions, Bryant Pond Dam could have passed about 20 percent of the PMF. This latter case was not modelled on the computer.

(4) Spillway Adequacy. The criteria for rating a spillway is presented in Appendix C. Since the dam cannot pass the 1/2 PMF, a further analysis was performed. It was assumed that Harveys Lake Dam would not fail. It was also assumed that no inflow occurred downstream of Bryant Pond Dam. In addition, it was assumed that Bryant Pond Dam would develop a breach 60 feet wide 0.1 hour after being overtopped by 0.3 foot. A breach of this size results in an outflow of about 8,300 cfs. The resulting outflow was routed downstream. The locations of cross sections used for routing are shown on Plate C-1. For the 3 percent PMF storm, the water surface near the recently constructed dwelling would increase 8.3 feet over the water surface that would occur if the dam did not fail. For the 1/2 PMF storm, there is not a significant increase in water surface because the peak storm flow, exclusive of any dam failure, is close to the peak flow with dam failure. The spillway capacity is rated as seriously inadequate.

## SECTION 6

### STRUCTURAL STABILITY

#### 6.1 Evaluation of Structural Stability.

##### a. Visual Observations.

(1) General. The visual inspection of Bryant Pond Dam, which is described in Section 3, resulted in a number of observations relevant to structural stability. These observations are evaluated herein for the various features.

(2) Embankment. Brush and trees growing on or near the embankment are undesirable. The performance history of the embankment indicates that excessive settlement has been occurring almost constantly since the embankment was completed. The records are replete with orders to raise and repair the embankment, especially the downstream rockfill. As none of the repairs were ever fully completed, as stated in the records, it is not possible to determine the amount of settlement occurring over any given period. As noted in Section 2, the initial poor construction practices may be the cause of the poor performance.

The seepage observed downstream from the embankment is significant. As some of the seepage areas are localized, they may indicate a flow concentration through parts of the embankment. As the area downstream from the embankment is covered with sediment and debris, and because seepage could be occurring beneath the sediment, a full assessment of the seepage is not possible.

As noted in Section 2, it is uncertain that the thin, unreinforced concrete core-wall was properly designed to sustain the anticipated loads. As the rockfill downstream settled, the passive pressures, which may have been relied upon in design, never fully developed. In its present state, the concrete of the core-wall is in good condition. The top section of the core-wall appears to have been overstressed and therefore failed. The core-wall beneath, where visible, appears to be close to vertical. However, judging by its present condition and performance



history, the core-wall cannot be relied upon to resist embankment loads or to act as a cutoff. As replacement of the core-wall would require the excavation of the embankment, the embankment is considered to be beyond repair.

(3) Appurtenant Structures. The conditions at the spillway are an indication of the lack of maintenance. The low side wall is a hydraulic design deficiency. The seepage observed from the toe of the embankment at each side of the spillway may be emanating from the spillway, judging by the open areas in the spillway walls and the cracks in the spillway slabs. Judging by the poor condition of the concrete conduits at the downstream end, it is not certain the outlet works conduits are watertight. Some of the seepage observed immediately downstream from the right conduit may have been emanating from the conduit. The Owner's plugging of the conduits was not totally successful. The upstream closure is unreliable. Furthermore, there is no way of drawing down the reservoir. As repair of the outlet works would require its complete replacement, the outlet works is considered to be beyond repair.

b. Design and Construction Data. There is no record of a stability analysis for the embankment or of a structural design for the core-wall. Both the design and the construction methods used, as previously described, are deficient.

c. Operating Records. There are no formal records of operation. As noted previously, the performance history of the embankment is poor.

d. Post-construction Changes. The records in the PennDER files indicate that the repairs that have been attempted were not accomplished adequately because of insufficient funding and lack of knowledge of good dam design and maintenance. Not repairing the washout, which presently exists on the embankment, leaves the core-wall with less downstream support than in other areas. In view of its performance history, this is of concern. The repairs made to the breach that was created during Tropical Storm Agnes are of major concern. The breached area was repaired with soil of unknown quality. The method of

placement is not known. The existing topwidth in this area is 6 feet. The upstream side of the repaired breach area is vertical for the upper 2 feet. The downstream side is vertical, at one area, for the upper 5 feet. A depression on the top of this area was noted. Should the repaired area become saturated, for whatever reason, the stability of the repaired area would be less than marginal. A failure of this area would re-create the breach caused during Tropical Storm Agnes. There is no certainty that the breach would not develop beyond its past size.

e. Seismic Stability. Bryant Pond Dam is located in Seismic Zone 1. Normally it can be considered that if a dam in this zone has adequate factors of safety under static loading conditions, it can be assumed safe for any expected earthquake loading. However, there is no evidence to suggest that the embankment would be stable during an earthquake.



SECTION 7  
ASSESSMENT, RECOMMENDATIONS, AND  
PROPOSED REMEDIAL MEASURES

7.1 Dam Assessment.

a. Safety.

(1) Based on visual inspection, available records, calculations, and past operational performance, Bryant Pond Dam is in very poor condition and is judged to be unsafe, emergency. With existing conditions, the spillway will pass only 2 percent of the PMF without overtopping the dam. A failure of the dam will increase the hazard to loss of life at one recently constructed home downstream. The spillway capacity is rated as seriously inadequate. The embankment has been overtopped twice in its operational history.

(2) Furthermore, excessive settlement has occurred on the embankment, especially on the downstream rockfill, over its entire operational history. This has contributed to the breaking of the concrete core-wall. At present, the core-wall is broken and tilted over the entire length of the dam, except where the dam was breached and subsequently repaired. As the core-wall cannot be relied upon to be effective, the embankment is considered to be beyond repair.

(3) The attempted repairs by the Owner were not designed or made in accordance with good engineering practice and are inadequate. The repairs to the breached area are unsafe.

(4) The outlet works is considered to be beyond repair. There is no means of drawing down the reservoir.

b. Adequacy of Information. The information available is such that an assessment of the condition of the dam can be inferred from the combination of visual inspection, past performance, and computations performed prior to and as part of this study.

c. Urgency. The recommendation in Paragraph 7.2 should be implemented immediately.

d. Necessity for Further Investigations. Accomplishment of the measure outlined in Paragraph 7.2 will not require further investigations by the Owner.

#### 7.2 Recommendations and Remedial Measures.

a. The following measure is recommended to be undertaken by the Owner immediately:

(1) Draw down the reservoir and then breach the dam. The breach should be of sufficient size that it is not possible to impound any significant quantity of water behind the dam during a flood. The method of breaching should be in accordance with good engineering practice. The breaching should be performed under the supervision of a professional engineer and it should be carefully accomplished by an experienced contractor to avoid creating a hazard downstream. Any structure that might replace the existing dam should be considered a new structure by the Commonwealth. Due consideration of the poor performance history of the existing features of the dam should be given before an attempt is made to incorporate them into a new structure.

SUSQUEHANNA RIVER BASIN  
HARVEYS CREEK, LUZERNE COUNTY  
PENNSYLVANIA

BRYANT POND DAM

NDI ID No. PA-00544  
DER ID No. 40-11


ESTATE OF GLENDORA BRYANT

PHASE I INSPECTION PROGRAM

JULY 1979

PLATES





HARVEYS  
LAKE

Shawnee


HARVEYS LAKE DAM  
AND ROADWAY CULVERT

HARVEYS CREEK

BREACHER  
DAM

2000  
SCALE:





Plan and Sections of Proposed Dam on Harvey's Creek


FOR


Samuel Raub Estate, Lake Township Luzerne Co Penna.

3-10-13


Sept 10, 1913

1/25 5 Miles  
ENGR






Section through Breast




Plan of Breast




Section of Breast

(Supplement 11-1-2)



Section through Breast



(Signature 11-1-3)

4/12-11

PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM  
BRYANT POND DAM  
ESTATE OF GLENDORA BRYANT

PLAN AND PROFILE


JULY 1979


3

PLATE 2



← *Up Stream*







Concrete Flumes 2'x2'

CROSS SECTION THROUGH BR  
OF  
Raub's Dam on Harveys Creek.  
Scale 20' = 1"

July 10



SH BREAST OF DAM AT SPILLWAY  
OF  
Creek, Lake Township Luzerne Co. Pa.  
July 18, 1914  
C. S. MILES  
ENGR.



PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM

BRYANT POND DAM

ESTATE OF GLENDORA BRYANT


SECTION

JULY 1979

PLATE 3

4





40'

Water Line

Steps 1' x 1 3/4'

40-11-7

14'9"

30'-0

SECTION OF SPILLWAY AT RAUB'S DAM


ON  
Creek, Lake Township, Luzerne Co., Pa.

1/2" = 1'

2

July 18, 1914.

C.S. Miles  
ENGR.



PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM

BRYANT POND DAM


ESTATE OF GLENDORA BRYANT

SPILLWAY PROFILE

JULY 1979

PLATE 4

3



BEYANT POND


TOP WATER ELEVATION 1103.30' 1-14-75

LINE

MATCH







PRELIMINARY

BRYANT POND LUZERNE COUNTY	
EXISTING POND	
SCALE: 1" = 50'	DRAWN: E. N. A.
DATE: JAN. 7, 1976	CHECKED: L. S.
SWENDEES & KOLESAR ASSOCIATES ENGINEERS & LAND SURVEYORS 100 EISEN STREET PO BOX 100 PO BOX, PA	
SHEET 2 OF 4	DEAD END ROAD

PHASE I INSPECTION REPORT NATIONAL DAM INSPECTION PROGRAM	
BRYANT POND DAM	
ESTATE OF GLENDORA BRYANT	
CONDITIONS IN JANUARY 1975	
JULY 1979	PLATE 5



SUSQUEHANNA RIVER BASIN  
HARVEYS CREEK, LUZERNE COUNTY  
PENNSYLVANIA

BRYANT POND DAM

NDI ID No. PA-00544  
DER ID No. 40-11

ESTATE OF GLENDORA BRYANT

PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM

JULY 1979

APPENDIX A

CHECKLIST - ENGINEERING DATA

## CHECKLIST

## ENGINEERING DATA

DESIGN, CONSTRUCTION, AND OPERATION  
PHASE INAME OF DAM: BURNETT POND

PA-00544

DER ID NO.: 40-11Sheet 1 of 4

ITEM	REMARKS
AS-BUILT DRAWINGS	SEE PLATES 2, 3, AND 4 "AS-BUILT" VARIES SIGNIFICANTLY FROM THE PLATES.
REGIONAL VICINITY MAP	SEE PLATE 1
CONSTRUCTION HISTORY	BUILT 1914
TYPICAL SECTIONS OF DAM	SEE "AS-BUILT" DRAWINGS.
OUTLETS: Plan Details Constraints Discharge Ratings	SEE PLATES 2 AND 3 NO RATINGS

A-1

## ENGINEERING DATA

Sheet 2 of 4

ITEM	REMARKS
RAINFALL/RESERVOIR RECORDS	NONE
DESIGN REPORTS	1914 PENNSYLVANIA WATER Supply Commission Report
GEOLOGY REPORTS	NONE
DESIGN COMPUTATIONS: Hydrology and Hydraulics Dam Stability Seepage Studies	NONE - SOME DATA IN 1914 PENNSYLVANIA WATER Supply Commission Report
MATERIALS INVESTIGATIONS: Boring Records Laboratory Field	NONE
POSTCONSTRUCTION SURVEYS OF DAM	SEE PLATE 5 FOR CONDITIONS IN JANUARY 1975.

A-2



## ENGINEERING DATA

Sheet 3 of 4

ITEM	REMARKS
BORROW SOURCES	Believed to be onsite.
MONITORING SYSTEMS	NONE
MODIFICATIONS	ADDITION OF ICE CHUTES, CIRCA 1938.
HIGH POOL RECORDS	SEE PRIOR ACCIDENTS BELOW
POSTCONSTRUCTION ENGINEERING STUDIES AND REPORTS	NONE RELEVANT TO EXISTING STRUCTURE
PRIOR ACCIDENTS OR FAILURE OF DAM: Description Reports	1933- OVERTOPPED BY 6" - NO DAMAGE 1972 - OVERTOPPED AND BREACHED

## ENGINEERING DATA

Sheet 4 of 4

ITEM	REMARKS
MAINTENANCE AND OPERATION RECORDS	NONE
SPILLWAY: Plan Sections Details	SEE PLATE 4 MUCH DATA IS LACKING.
OPERATING EQUIPMENT: Plans Details	SEE PLATE 3 NO DETAILS AVAILABLE.
PREVIOUS INSPECTIONS Dates Deficiencies	SEE FOLLOWING SHEETS

A-4

GANNETT FLEMING CORDRY  
AND CARPENTER, INC.  
HARRISBURG, PA.

SUBJECT PREVIOUS INSPECTIONS FILE NO. \_\_\_\_\_  
SHEET NO. 1 OF \_\_\_\_\_ SHEETS  
FOR \_\_\_\_\_  
COMPUTED BY \_\_\_\_\_ DATE \_\_\_\_\_ CHECKED BY \_\_\_\_\_ DATE \_\_\_\_\_

ABBREVIATIONS: PWSC = PENNSYLVANIA WATER  
Supply Commission  
DER = PENNSYLVANIA DEPARTMENT  
OF ENVIRONMENTAL  
RESOURCES, ALSO AS  
PREVIOUSLY KNOWN,  
THE WATER POWER  
AND RESOURCES BOARD, AND  
THE DEPARTMENT OF  
FORESTS AND WATERS.  
PFC = PENNSYLVANIA FISH  
COMMISSION.

INSPECTION, DATE, BY WHOM, AND COMMENTS  
DOES NOT INCLUDE INSPECTIONS DURING  
CONSTRUCTION.

JULY 1919 by PWSC FLASH BOARDS ON SPILLWAY,  
LOWER TOE WET AND SOGGY, CORE WALL CRACKED  
IN SEVERAL PLACES, SPILLWAY CONCRETE DEFINING  
WALLS HAVE COLLAPSED AND ABUTMENTS ARE  
CRACKED AT THE RIGHT ABUTMENT COREWALL, HAVING  
SETTLED PERCEPTIBLY. DOWNSSTREAM ROCKFILL  
AT RIGHT SIDE OF SPILLWAY HAS SETTLED  
14 INCHES. LEAKAGE TOE DOWNSSTREAM FILL AT  
RIGHT.

ORDERED TO REPAIR DAM - August 12, 1919  
OWNER REPORTED ON September 7, 1919 THAT  
REPAIRS WOULD COMMENCE AT ONCE

MAY 1920 by PWSC The downstream rock fill  
appears to have settled and the pressure  
of the earth and water upstream has pushed  
the core wall so that it is out of plumb  
for nearly its entire length, with cracks  
showing near each end. Spillway abutments  
poor, concrete disintegrating and broken.  
Flashboards in right spillway bay. Wasteway  
channel - poor conditions - side walls gone. There

A-5

IS MORE OR LESS FLOW OF WATER ALONG THE  
DOWNSTREAM TOE AND BELOW THAT IT IS SWAMPY;  
(NOTES THAT THERE USED TO BE 2 SPRINGS,  
PRE-CONSTRUCTION, ONE 50' RIGHT OF SPILLWAY AND  
ANOTHER NEAR THE RIGHT END OF THE DAM.

Repairs ordered July 1920.

Owner discussed with PWSC August 1920; Owner  
was informed that repairs could be delayed  
a year.

JUNE 1922 by PWSC NOTES NEW OWNER BRYANT AND  
WILLIAMS. CREST UNEVEN. DOWNSTREAM FACE ROUGH.  
CORE WALL LEANING DOWNSTREAM DUE TO EITHER  
SETTLEMENT OF ROCKFILL ON DOWNSTREAM SIDE  
OR ICE PRESSURE. CONSIDERABLE LEAKAGE, SWAMPY  
AT LOWER TOE. WASTEWAY CHANNEL - POOR DISINTEGRATING.  
NOTES CONSTRUCTION OF ICE HOUSE.

Repairs ordered September 1922

NO RESPONSE IN RECORD.

JULY 1923 by PWSC. DOWNSTREAM FACE ROUGH  
AND UNEVEN, CORE-WALL LEANING DOWNSTREAM,  
WASTEWAY - POOR, DISINTEGRATING. MARSHY AT LOWER TOE.  
POOR DESIGN AND POOR CONSTRUCTION. REPAIRS MADE  
TO RIGHT SPILLWAY ABUTMENT BUT WALL HAS  
NOT BEEN (ILLEGIBLE) HIGH ENOUGH. REPAIRS  
WILL BE MADE TO LEFT WALL IN NEAR FUTURE.  
REPAIRS (ILLEGIBLE) DONE TO DOWNSTREAM SIDE  
OF SPILLWAY IN WHICH SOME OF THE LARGER  
HOLES WERE FILLED WITH ROCK AND MORTAR  
CONCRETE POSTS AND IRON PIPES IN SPILLWAY.  
NOTES THAT MR. BRYANT APPEARS TO WANT  
THE DAM IN GOOD REPAIR. SOME MINOR  
REPAIRS HAVE BEEN MADE SINCE LAST  
INSPECTION. PWSC INSPECTOR SUGGESTED THAT  
NEW WALLS BE BUILT AT THE SPILLWAY AND  
A-6



THAT THE SECTION OF CORE WALL EXTENDING ABOVE THE TOP OF THE DAM BE REMOVED. 1924 by OWNER. No deficiencies, good condition, spillway being repaired.

1924 by DER. DAM CREST UNEVEN, UPSTREAM FACE UNEVEN. UPSTREAM FILL HAS SETTLED AND APPEARS TO BE ABOUT A FOOT LOWER THAN THE DOWNSTREAM FILL THRU THE MIDDLE SECTION OF THE DAM. CONSIDERABLE LEAKAGE. SIDE WALLS OF SPILLWAY APRON NEARLY ALL GONE AND WATER FLOWS THRU ROCK FILL AT SIDES OF APRON. OUTLET LEAKS. LOWER TOE SWAMPY. PICKS AND PILES FOR FLASHBOARDS IN SPILLWAY. THERE IS A CONCRETE SLUICE 18" WIDE AND 3' DEEP THRU THE TOP OF THE DAM. UPSTREAM FILL HAS SETTLED NEAR THE SPILLWAY AND HAS BEEN REPAIRED BY FILLING WITH ROCK.

MAY 1926 by DER. DAM CREST UNEVEN, DOWNSTREAM FACE STEEP AND UNEVEN. SETTLEMENT: UPSTREAM PORTION 2'± BELOW TOP OF CORE-WALL. THE CORE-WALL IN THIS DAM LEANS DOWNSTREAM AND THE ROCK FILL ON THE DOWNSTREAM SIDE APPEARS TO HAVE MOVED. THERE IS MORE OR LESS LEAKAGE. WATER CAN BE HEARD RUNNING THROUGH THE UPSTREAM FILL AND THROUGH THE CORE-WALL NEAR THE MIDDLE. IT WAS SUGGESTED TO THE SUPERINTENDENT, ..., THAT ADDITIONAL EARTH BE ADDED TO THE UPSTREAM SIDE, FIRST REMOVING THE ROCK AND UNCOVERING THE ORIGINAL EARTH FILL AND THEN REPLACING THE ROCK, AND THAT ADDITIONAL ROCK FILL BE ADDED TO THE DOWNSTREAM SIDE WITH A TOP WIDTH OF FROM 6 TO 7 FEET.

Repairs ORDERED JUNE 1926  
Repairs ORDERED NOVEMBER 1926

A-7

GANNETT FLEMING CORDDRY  
AND CARPENTER, INC.  
HARRISBURG, PA.

SUBJECT \_\_\_\_\_ FILE NO. \_\_\_\_\_  
SHEET NO. 4 OF \_\_\_\_\_ SHEETS  
FOR \_\_\_\_\_  
COMPUTED BY \_\_\_\_\_ DATE \_\_\_\_\_ CHECKED BY \_\_\_\_\_ DATE \_\_\_\_\_

Repairs ordered January 1927

OCTOBER 1927 CREST OF DAM UNEVEN, UPSTREAM FACE UNEVEN, DOWNSTREAM FACE UNEVEN, SETTLEMENT IS NOTICEABLE ON BOTH UPSTREAM AND DOWNSTREAM SIDES. SPILLWAY ABUTMENTS FAIR. FLASHBOARD SUPPORTS IN SPILLWAY. WASTEWAY CHANNEL O.K. EXCEPT AT DOWNSTREAM END WHERE THERE IS SOME UNDERMINING. CONSIDERABLE LEAKAGE. NOTE: DISCUSSED REPAIRS WITH MR. BRYANT AND SUGGESTED THE REMOVAL OF PIERS AND PILES FROM THE SPILLWAY, AND THAT THE DOWNSTREAM ROCK FILL BE WIDENED AND RAISED, AND THAT THE SLOPE BE FLATTENED. THE CONCRETE CUTOFF WALL APPEARS TO LEAN MORE THAN WHEN LAST EXAMINED.

AUGUST 1928 CREST OF DAM UNEVEN, UPSTREAM FACE POOR. DOWNSTREAM FACE UNEVEN, STEEP. CONSIDERABLE SETTLEMENT ON THE UPSTREAM AND DOWNSTREAM SIDES OF THE CORE-WALL WHICH HAS BEEN PUSHED DOWNSTREAM 1 FOOT OR MORE AT THE TOP AND IS DECIDEDLY OUT OF PLUMB THRU THE CENTRAL PORTION OF THE DAM. CONSIDERABLE LEAKAGE THRU THE ENTIRE LENGTH OF THE DAM. OUTLETS LEAK, LOWER TOE SWAMPY. RIGHT SPILLWAY ABUTMENT WALL UPSTREAM OF THE CUTOFF TIPPED OVER; THE LEFT ONE IS IN FAIR CONDITION. FLASH BOARD SUPPORTS AND A PORTION OF THE RIGHT UPSTREAM SPILLWAY ABUTMENT ARE IN THE SPILLWAY.

Repairs ordered August 1928, NOTING NO ACTION ON PREVIOUS ORDERS.

September 1928 DER met with Mr. Bryant & Mr. Williams at the dam. They were requested to widen the downstream rock fill so that it would be 8' wide at top with a downstream slope of 1V on 2H. Messrs Bryant thought this could be done during the winter by drawing the stone from a nearby hillside down to the pond and over the ice to the dam.

November 1929 by DER. There is some leakage through the outlet at the right of the spillway. The lower toe is wet and swampy. The dam crest is narrow and low and part of the coke wall, through the central section of the structure, has fallen over and been removed. The downstream slope is too steep. Part of the work previously recommended has been done, but in a very unsatisfactory manner; stone having been piled up to obtain the topwidth and making the downstream slope steeper instead of flatter as was recommended. There is some leakage at the left of the spillway, a heavy leak about 60 feet to the right of the spillway and some leakage at about 100 feet to the right of the spillway. The spillway abutment wings have been repaired and are in fair condition but they have not been built to a height that would prevent water from flowing over them and damaging the



EMBANKMENT. THERE ARE TWO VERTICAL  
PIPES ON THE SPILLWAY CREST WHICH  
APPARENTLY WERE INTENDED TO SUPPORT  
FLASHBOARDS. THE LOWER END OF THE  
SPILLWAY APRON SHOULD BE PROTECTED  
BY RIPRAP.

REPAIRS ORDERED NOVEMBER 1929

REPAIRS AGAIN ORDERED DECEMBER 1929

LETTER MR. BRYANT TO DER - DECEMBER 1929

"... THE DAM HAS BEEN DRAINED  
AND WORK DONE ON THE INSIDE  
BY CONCRETING CREVICES AND FILLING  
IN WITH DIRT, I WAS NOT ASKED  
TO DO. HOWEVER, IF THE SLOPE IS  
TO STEEP ON THE OUTSIDE, NOT  
WIDE ENOUGH ON TOP I WILL  
DO THAT THIS WINTER."

LETTER DER TO MR. BRYANT - JANUARY 1930

REITERATED 8 FOOT TOPWIDTH AND  
1V ON 2H SLOPE FOR ROCKFILL.

JULY 1931 BY DER. SETTLEMENT: THERE MUST  
HAVE BEEN CONSIDERABLE SINKING DOWNSTREAM.  
9" FLASHBOARDS IN SPILLWAY. OUTLET LEAKS.  
THE CREST (OF DAM) IS NARROW; THE TOP  
OF THE ROCK FILL BELOW THE CORE BEING  
ONLY 4 OR 5 FEET WIDE. THE TOP OF THE  
CREST WALL IS TIPPED BADLY DOWNSTREAM.  
THE DOWNSTREAM FACE IS TOO STEEP  
(ABOUT 1V ON 1.25H). NOTHING HAS BEEN DONE  
TO FLATTEN IT. THERE IS SOME LEAKAGE  
TO THE LEFT OF THE SPILLWAY AND THRU  
OUTLET TO RIGHT OF SPILLWAY; HEAVY LEAK  
UNDER HIGH SECTION AT MIDDLE; SMALL LEAK  
AT PIPE TOWARD RIGHT END. NOTE: MR. BRYANT

A-10



HAS DUMPED ADDITIONAL STONES ON TOP OF  
THE DOWNSTREAM FILL TWICE, AND MAY ADD  
MORE.

Repairs ordered July, 1931 AND  
THREATENING LEGAL ACTION IF  
NOT ACCOMPLISHED.

LETTER MR. BRYANT TO DER, JULY 1931,  
NOTING HE "HAD ADDED STONE  
TO THIS DAM THREE DIFFERENT  
TIMES AS PER THE REQUEST  
OF A DIFFERENT INSPECTOR EACH  
TIME ON THE JOB. I AM WORKING  
ON THE DAM NOW AND....."

November 1931 by DER (IN MEMO) CONSIDERABLE  
ROCK HAS BEEN ADDED THIS SEASON TO THE  
DOWNSTREAM FILL. THE TOP WIDTH OF THE  
ROCK DOWNSTREAM FROM THE CORE WALL IS  
NOW ABOUT 6' NEAR THE SPILLWAY WITH  
A 1V ON 2H SLOPE, AND ABOUT 7 FEET NEAR  
THE ICE HOUSE WITH A 1V ON 1.25H SLOPE. FOR  
THE FULL TOPWIDTH OF DAM, INCLUDING THE  
UPSTREAM FILL AND CORE WALL, ABOUT 5 FEET  
MORE MAY BE ADDED, MAKING THE TOTAL  
TOPWIDTH 11 TO 12 FEET.

October 1932 by DER. "IT DID NOT APPEAR  
THAT ANY WORK HAD BEEN DONE SINCE  
THE LAST EXAMINATION, AND THE SLOPE OF  
THE DOWNSTREAM EARTH FILL IS STILL TOO  
STEEP. ...."

Repairs ordered October 1932  
LETTER FROM MR. BRYANT TO DER  
October 1932  
(ON NEXT SHEET)

A-11

"OF FOUR DAMS THAT I LEASE THIS ONE IS IN THE BEST SHAPE. I WILL GET SOME MEN WHEELING ROCK AT THE STEEPEST PLACE ALTHOUGH I DON'T KNOW WHAT TO PAY THEM WITH. I KEEP THE WATER LEVEL LOWER. THERE IS ONLY ONE FAMILY LIVING BELOW AND THEY ARE ON MY FARM, THE REST IS OWNED BY THE WATER COMPANY AND WASTE LAND.

ROCK IS SCARCE ON THIS FARM AND THAT SLOPE SEEMS TO TAKE AN AWFUL LOT. WILL STOP SOME DAY AT CAPITOL AND GO OVER THINGS, MEAN WHILE WILL GET DONE WHAT I CAN."

OCTOBER 1933 BY DER (MEMO) "MR. BRYANT SAID THAT HE HAS A FARMER HAULING STONE ONTO THE DOWNSTREAM SIDE OF THIS DAM FOR TWO MONTHS THIS SEASON, BUT THE WRITER WOULD SCARCELY HAVE KNOWN IT FROM ITS APPEARANCE." TOP WIDTH OF ROCKFILL IS GENERALLY LESS THAN 8'. SLOPE IS STILL 1V ON 1.25H IN PLACES. NOTED RECENT OVERTOPPING TO DEPTH OF 6". NO HARM FROM OVERTOPPING EXCEPT SLIGHT SETTLEMENT OF THE CREST OF THE ROCKFILL. LOWEST STEP OF SPILLWAY BROKEN AWAY AT RIGHT END, STREAM FLOWING BELOW THIS WASHED AWAY. "MR. BRYANT SAID THAT HE WOULD HAVE THE SPILLWAY REPAIRED AND WOULD CONTINUE TO ADD STONE FILL AS THE OPPORTUNITY OFFERED".

AUGUST 1934 by DER (MEMO) Spillway has been repaired. Part of the crest wall behind the house is tipped over. "MR. BRYANT SAID THAT HE PUSHED IT OVER WITH HIS FOOT; THIS WALL SERVES NO PURPOSE ANYWAY." NO MORE ROCK ADDED TO DOWNSTREAM SLOPE.

DECEMBER 1935 by DER UPSTREAM FACE UNEVEN AND LOW. THE ROCKFILL ON THE DOWNSTREAM FACE WAS NEVER BUILT UP TO THE CREST OF THE DAM. THERE IS GENERAL SETTLEMENT OF THE EMBANKMENT AND ROCKFILL. CONSIDERABLE LEAKAGE. THE TOP OF THE CORE WALL THROUGHOUT MOST OF THE LENGTH IS LEAKING DOWNSTREAM, AND ABOUT 200 FEET OF IT HAS FALLEN OVER.

THE RIGHT ABUTMENT OF THE SPILLWAY IS LEAKING INTO THE SPILLWAY. FLASHBOARDS IN SPILLWAY.

Repairs ORDERED JANUARY 1936.

JUNE 1938 by DER (MEMO). STRUCTURE "ABOUT THE SAME CONDITION AS PREVIOUSLY", EXCEPT THE FLASHBOARDS HAD BEEN REMOVED. NOTES CONSTRUCTION OF 2 SLUICES. "MR. BRYANT SAID HE HAS ADDED STONE TO THE DOWNSTREAM FACE FROM TIME TO TIME, AND DOES NOT FEEL HE CAN ENTAIL ANY FURTHER EXPENSE."

JULY 1952 by DER AND PFC (MEMO) "COMPLETE DISREPAIR". CORE WALL CRACKED AT 6'-10' CENTERS. PORTION OF WALL ABOVE EMBANKMENT, ABOUT 4 FEET, HAS FALLEN AT SEVERAL POINTS. THE ENTIRE EMBANKMENT LEAKS EXTENSIVELY AND WATER CAN BE HEARD RUNNING THROUGH THE STRUCTURE.

GANNETT FLEMING CORDDRY  
AND CARPENTER, INC.  
HARRISBURG, PA.

SUBJECT \_\_\_\_\_ FILE NO. \_\_\_\_\_  
SHEET NO. 10 OF \_\_\_\_\_ SHEETS  
FOR \_\_\_\_\_  
COMPUTED BY \_\_\_\_\_ DATE \_\_\_\_\_ CHECKED BY \_\_\_\_\_ DATE \_\_\_\_\_

MAY 1964 by DER. CORE WALL LEANS AT ABOUT 30-45° ANGLE. SPILLWAY ABUTMENT CONCRETE CRACKED AND BROKEN. LEAKAGE AT LOWER TOE.

OCTOBER 1975 by DER (MEMO). "DURING STORM ELOISE A PORTION OF THE CONCRETE WALL BROKE OFF AND FELL DOWNSTREAM. THIS ..... IN REALITY ADDS LENGTH TO THE SPILLWAY SINCE THE BREAK IS AT SPILLWAY GRADE. THE CONCRETE THAT BROKE OFF IS ACTING AS A SCOUR PIN." "



SUSQUEHANNA RIVER BASIN  
HARVEYS CREEK, LUZERNE COUNTY  
PENNSYLVANIA

BRYANT POND DAM

NDI ID No. PA-00544  
DER ID No. 40-11

ESTATE OF GLENDORA BRYANT

PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM

JULY 1979

APPENDIX B  
CHECKLIST - VISUAL INSPECTION

CHECKLIST

VISUAL INSPECTION

PHASE I

Name of Dam: BRYANT POND County: LUZERNE State: PENNSYLVANIA  
 ID No.: PA-00544 DER ID No.: 40-11  
 Type of Dam: EARTHILL AND ROCKILL w/ CONCRETE CORE-WALL Hazard Category: HIGH  
 Date(s) Inspection: 11 JUNE 1979 Weather: HAZY - OCCASIONAL LIGHT RAIN Temperature: 60°F  
Soil Conditions - Moist

Pool Elevation at Time of Inspection: 1105.3 msl/Tailwater at Time of Inspection: 1093.2 msl




Inspection Personnel:

B. BRYANT (OWNER)  
D. Wilson (GFCC)  
D. Ebersole (GFCC)

A. WHITMAN (GFCC) Recorder


# EMBANKMENT

Sheet 1 of 2

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS	1'x2'x6" depression IN BREACH AREA	
UNUSUAL MOVEMENT OR CRACKING AT OR BEYOND THE TOE	TYPICAL CROSS SECTION EXCEPT AT BREACH AREA:	
SLOUGHING OR EROSION: Embankment Slopes Abutment Slopes		CRACKOUT
CREST ALIGNMENT: Vertical Horizontal	HORIZONTAL - NO OBSERVED disturbances VERTICAL - SEE SURVEY DATA FOLLOWING INSPECTION FORM	
RIPRAP FAILURES	UNPROTECTED UPSTREAM SLOPE.	

# EMBANKMENT

Sheet 2 of 2

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
JUNCTION OF EMBANKMENT WITH: Abutment Spillway Other Features	LEFT ABUTMENT BEYOND SPILLWAY RIGHT ABUTMENT NO DEFICIENCIES	 <p>PLAN ELEV TOP OVERHANGS 3"</p>
ANY NOTICEABLE SEEPAGE	SEE PLATE B-1	
STAFF GAGE AND RECORDER	NONE	
DRAINS	NONE	
BRUSH	ON UPSTREAM SLOPE EXCEPT BENCH AREA AND AT RIGHT ABUTMENT OF DOWNSTREAM SLOPE	



# OUTLET WORKS

Sheet 1 of 1

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CRACKING AND SPALLING OF CONCRETE SURFACES IN OUTLET CONDUIT	APPEARS LIKE DRY MASONRY. FLOW IN SPILLWAY VISIBLE THROUGH LEFT CONDUIT WALL.	
INTAKE STRUCTURE	FOUR SHEARER COLUMNS IN RESERVOIR IS ALL THAT REMAINS.	
OUTLET STRUCTURE	FREE OUTFALL 10FS FLOW FROM RIGHT CONDUIT	
OUTLET CHANNEL	NATURAL STREAM	
EMERGENCY GATE	IN OPERABLE	OWNER REPORTED PREVIOUS ATTEMPT AT PLUGGING CONDUITS NOT ENTIRELY SUCCESSFUL.

# UNGATED SPILLWAY

Sheet 1 of 1

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE WEIR	UNEVEN - SEE SURVEY DATA FOLLOWING INSPECTION FORMS.	
APPROACH CHANNEL	RESERVOIR	
DISCHARGE CHANNEL	CASCADE - CONCRETE SLABS, JOINTS AT EDGES AND GABRIEL THROUGH.	
BRIDGE AND PIERS	NONE	

# INSTRUMENTATION

Sheet 1 of 1

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
MONUMENTATION/SURVEYS	NONE	
OBSERVATION WELLS	NONE	
WEIRS	NONE	
PIEZOMETERS	NONE	
OTHER	NONE	

# RESERVOIR AND WATERSHED


Sheet 1 of 1

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SLOPES	Rolling Hills Some Swamps	
SEDIMENTATION	OWNER REPORTS SIGNIFICANT SEDIMENT AFTER TROPICAL STORM AGNES	
WATERSHED DESCRIPTION	Below Harveys LAKE DAM. WOODEN MINOR DEVELOPMENT	FOR HARVEYS LAKE DAM - SEE APPENDIX C




# DOWNSTREAM CHANNEL

Sheet 1 of 1

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONDITION: Obstructions Debris Other	Small bridge 200' downstream	NEGLECTIBLE
SLOPES	Fairly mild	
APPROXIMATE NUMBER OF HOMES AND POPULATION	1 recently constructed home upstream of roadway embankment at right	4-6' dia CMP 200' to dwelling 
CONTINUED	DOWNSTREAM OF ABOVE EMBANKMENT ABOUT 5 HOMES OR LEFT BANK FAIRLY HIGH.	
	Also downstream is HARVEYS CREEK CANAL DIVERSION STRUCTURE	Owned by PENNSYLVANIA GAS AND WHITE.


GANNETT FLEMING CORDDRY  
AND CARPENTER, INC.  
HARRISBURG, PA.

SUBJECT LEITCH POND DAM FILE NO. 7822  
SHEET NO. 1 OF 1 SHEETS  
FOR ASCC DAM INSPECTION  
COMPUTED BY DLC DATE \_\_\_\_\_ CHECKED BY \_\_\_\_\_ DATE \_\_\_\_\_



GANNETT FLEMING CORDRY  
AND CARPENTER, INC.  
HARRISBURG, PA.

SUBJECT DRYING POND DAM FILE NO. 7832  
SHEET NO. 1 OF 1 SHEETS  
FOR USE OF THE DESIGNER  
COMPUTED BY \_\_\_\_\_ DATE \_\_\_\_\_ CHECKED BY \_\_\_\_\_ DATE \_\_\_\_\_




NOTE: There is NO RELIABLE DATUM AT THE DAM. TO CORRELATE THE SURVEY DATA WITH THE PLATES, IT WAS ASSUMED THAT THE HIGH POINT OF THE SPIWAY, EL 1105.17 = EL 92.0 ON PLATES

DATUM FOR PLATE 5 IS UNKNOWN

DRYING POND DAM.


GANNETT FLEMING CORDDRY  
AND CARPENTER, INC.  
HARRISBURG, PA.

SUBJECT BRYANT POND DAM FILE NO. 7822  
SHEET NO. 1 OF 1 SHEETS  
FOR ASCE - DAM INSPECTION  
COMPUTED BY \_\_\_\_\_ DATE \_\_\_\_\_ CHECKED BY \_\_\_\_\_ DATE \_\_\_\_\_



B-II





PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM

BRYANT POND DAM

ESTATE OF GLENDORA BRYANT

RESULTS OF VISUAL INSPECTION

JULY 1979

PLATE B-1

SUSQUEHANNA RIVER BASIN  
HARVEYS CREEK, LUZERNE COUNTY  
PENNSYLVANIA

BRYANT POND DAM

NDI ID No. PA-00544  
DER ID No. 40-11

ESTATE OF GLENDORA BRYANT  
PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM

JULY 1979

APPENDIX C  
HYDROLOGY AND HYDRAULICS

## APPENDIX C

### HYDROLOGY AND HYDRAULICS

In the recommended Guidelines for Safety Inspection of Dams, the Department of the Army, Office of the Chief of Engineers (OCE), established criteria for rating the capacity of spillways. The recommended Spillway Design Flood (SDF) for the size (small, intermediate, or large) and hazard potential (low, significant, or high) classification of a dam is selected in accordance with the criteria. The SDF for those dams in the high hazard category varies between one-half of the Probable Maximum Flood (PMF) and the PMF. If the dam and spillway are not capable of passing the SDF without overtopping failure, the spillway capacity is rated as inadequate. If the dam and spillway are capable of passing one-half of the PMF without overtopping failure, or if the dam is not in the high hazard category, the spillway capacity is not rated as seriously inadequate. A spillway capacity is rated as seriously inadequate if all of the following conditions exist:

- (a) There is a high hazard to loss of life from large flows downstream of the dam.
- (b) Dam failure resulting from overtopping would significantly increase the hazard to loss of life downstream from the dam from that which would exist just before overtopping failure.
- (c) The dam and spillway are not capable of passing one-half of the PMF without overtopping failure.

# APPENDIX C

SUSQUEHANNA River Basin

Name of Stream: HARVEYS CREEK

Name of Dam: BRYANT POND

ND<sup>I</sup> ID No.: PA-00544

DER ID No.: 40-11

Latitude: N 41° 19' 00" Longitude: W 76° 04' 15"

Top of Dam (low spot) Elevation: 1106.7

Streambed Elevation: \_\_\_\_\_ Height of Dam: \_\_\_\_\_ ft

Reservoir Storage at Top of Dam Elevation: \_\_\_\_\_ acre-ft

Size Category: SMALL

Hazard Category: HIGH (see Section 5)

Spillway Design Flood: Varies 1/2 PMF to PMF

USE 1/2 PMF BECAUSE OF SMALL  
DOWNSTREAM POPULATION.

## UPSTREAM DAMS

Name	Distance from Dam (miles)	Height (ft)	Storage at top of Dam Elevation (acre-ft)	Remarks
<u>HARVEYS LAKE</u>	<u>2.7</u>	<u>3±</u>	<u>N/A</u>	<u>NATURAL LAKE</u>
	<u>ALONG</u>			
	<u>STREAM</u>			

## DOWNSTREAM DAMS

<u>PENNSYLVANIA</u>				
<u>GAS &amp; WATER</u>				<u>IGNORED IN</u>
<u>HARVEYS CREEK</u>				
<u>CANAL DIVERSION</u>				<u>ANALYSIS</u>
<u>STRUCTURE</u>				



SUSQUEHANNA River Basin

Name of Stream: HARVEYS CREEK

Name of Dam: BRYANT POND

NDS ID No.: \_\_\_\_\_

DBR ID No.: \_\_\_\_\_

Latitude: N 41° 19' 00" Longitude: W 76° 04' 15"

DETERMINATION OF PMF RAINFALL

For Area A

which consists of Subareas A1 of 6.62 sq. mile

A2 7.6

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Total Drainage Area 14.22 sq. mile

PMF Rainfall Index = 22.15 in., 24 hr., 200 sq. mile


Zone	Hydromet. 40 (Susquehanna Basin)	Hydromet. 33 (Other Basins)
	<u>N/A</u>	<u>N/A</u>
Geographic Adjustment Factor	<u>98%</u>	<u>1.0</u>
Revised Index Rainfall	<u>21.7</u>	<u>N/A</u>

RAINFALL DISTRIBUTION (percent)

<u>Time</u>	<u>Percent</u>
6 hours	<u>114</u>
12 hours	<u>123</u>
24 hours	<u>133</u>
48 hours	<u>139</u>
72 hours	<u>142</u>
96 hours	<u>N/A</u>

GANNETT FLEMING CORDRY  
AND CARPENTER, INC.  
HARRISBURG, PA.

SUBJECT \_\_\_\_\_ FILE NO. \_\_\_\_\_  
SHEET NO. \_\_\_\_\_ OF \_\_\_\_\_ SHEETS  
FOR \_\_\_\_\_  
COMPUTED BY \_\_\_\_\_ DATE \_\_\_\_\_ CHECKED BY \_\_\_\_\_ DATE \_\_\_\_\_




SKETCH OF SYSTEM

FOR LOCATION OF  
ROUTING SECTIONS,  
SEE PLATE C-1

C-4

GANNETT FLEMING CORDRY  
AND CARPENTER, INC.  
HARRISBURG, PA.

SUBJECT HARVEY'S LAKE DAM FILE NO. 7822  
SHEET NO. 1 OF 1 SHEETS  
FOR USCE - DAM INSPECTION  
COMPUTED BY \_\_\_\_\_ DATE \_\_\_\_\_ CHECKED BY \_\_\_\_\_ DATE \_\_\_\_\_




LOOKING UPSTREAM  
HARVEY'S LAKE DAM  
Profile - Top of Dam  
1253 - 1255: 16.5' - 16.5' - 16.5' - 16.5'

C-5

GANNETT FLEMING CORDRY  
AND CARPENTER, INC.  
HARRISBURG, PA.

SUBJECT Profile D.I. of Highway FILE NO. 7822  
WISCONSIN SHEET NO. 1 OF 1 SHEETS  
 FOR WISCONSIN HIGHWAY  
 COMPUTED BY \_\_\_\_\_ DATE \_\_\_\_\_ CHECKED BY \_\_\_\_\_ DATE \_\_\_\_\_





Data for Dam at Outlet of Subarea A1  
(see Sketch on Sheet C-4)

Name of Dam: HARVEYS LAKE

Height: 3 FT ± (existing)

Spillway Data:

	Existing Conditions	Design Conditions
Top of Dam Elevation	<u>SEE NEXT 2 SHEETS</u>	
Spillway Crest Elevation		
Spillway Head Available (ft)		
Type Spillway		
"C" Value - Spillway		
Crest Length - Spillway (ft)		
<u>Spillway</u> Peak Discharge (cfs)		
Auxiliary Spillway Crest Elevation		
Auxiliary Spillway Head Available (ft)		
Type Auxiliary Spillway		
"C" Value - Auxiliary Spillway		
Crest Length - Auxiliary Spillway (ft)		
<u>Auxiliary Spillway</u> Peak Discharge (cfs)		
<u>Combined Spillway</u> Discharge (cfs)		



Spillway Rating Curve: FROM 2 FOLLOWING SHEETS

Elevation	<u>Q Spillway (cfs)</u>	<u>Q Auxiliary Spillway (cfs)</u>	<u>Combined (cfs)</u>
<u>1255</u>			<u>0</u>
<u>1256</u>			<u>53</u>
<u>1257</u>			<u>198</u>
<u>1258</u>			<u>422</u>
<u>1259</u>			<u>491</u>
<u>1260</u>			<u>549</u>
<u>1261</u>			<u>601</u>
<u>1262</u>			<u>649</u>
<u>1263</u>			<u>694</u>
<u>1264</u>			<u>736</u>

GANNETT FLEMING CORDDRY  
AND CARPENTER, INC.  
HARRISBURG, PA.

SUBJECT \_\_\_\_\_ FILE NO. \_\_\_\_\_  
SHEET NO. \_\_\_\_\_ OF \_\_\_\_\_ SHEETS  
FOR \_\_\_\_\_  
COMPUTED BY \_\_\_\_\_ DATE \_\_\_\_\_ CHECKED BY \_\_\_\_\_ DATE \_\_\_\_\_

# HARVEYS LAKE OUTLET




USE BROAD CRESTED WEIR  $C = 2.7$

$$Q = CLH^{1.5}$$

$$Q = 2.7 (16.5 \times (\text{POOL} - 1255)^{1.5} + 18 \times (\text{POOL} - 1255.7)^{1.5} + 87.5 \times (\text{POOL} - 1257.8)^{1.5})$$

POOL	Q (CFS)
1255	0
1255.7	26
1256	53
1257	198
1257.8	357
1258	422
1259	958
1260	1702

# HARVEYS LAKE OUTLET ROADWAY & CULVERT



$$A_{\text{CULVERT}} = \frac{\pi (10)^2}{8} = 39.27 \text{ FT}^2$$

$$P = 5\pi + 10 = 25.71 \text{ FT}$$

$$R = A/P = 1.53 \text{ FT}$$

$$K_s = \frac{29.1 \text{ m}^2 L}{R^{4/3}} = .15$$

$$K_{\text{ENTRANCE}} = 0.5$$

$$K_{\text{EXIT}} = 1.0$$

$$\Sigma K = 1.65$$

$$Q_{\text{CULVERT}} = A \sqrt{\frac{2gH}{\Sigma K}} = 39.27 \sqrt{\frac{2gH}{1.65}}$$

$$= 245.3 \sqrt{(P_{\text{POOL}} - 1255)}$$

NOTE: \* INDICATES CONTROL

POOL	Q CFS CULVERT	Q CFS LAKE OUTLET
1255	0	0 *
1256	245	53 *
1257	347	198 *
1257.8	410	357 *
1258	425	422 *
1259	491 *	958
1260	549 *	1702
1261	601 *	N/A
1262	649 *	
1263	694 *	
1264	736 *	

A1

Name of Dam: HARVEYS LAKE

[illegible]

**\*\* Planimetered contour at least 10 feet above top of dam**

Reservoir Area at Top of Dam is 16 percent of watershed.

Remarks:



SUSQUEHANNA River Basin

Name of Stream: HARVEYS CREEK

Name of Dam: BRYANT POND

NDS ID No.: \_\_\_\_\_

DER ID No.: \_\_\_\_\_

Latitude: N 41° 19' 00" Longitude: W 76° 04' 15"

Drainage Area: 14.22 sq. mile

Data for Subarea: A1 (see Sketch on Sheet C-4)

Name of Dam at Outlet of Subarea: HARVEYS LAKE

Drainage Area of Subarea: 6.62 sq. mile

Subarea Characteristics:

Assumed Losses: 1.0-inch initial abstraction + 0.05 in/hr

The following are measured from outlet of subarea to the point noted:

L = Length of Main Watercourse extended to the divide = N/A mile

LCA = Length of Main Watercourse to the centroid = N/A mile

From NAB Data: AREA 12, PLATE F  
CENTROID FALLS IN LAKE

Cp = 0.30

C<sub>T</sub> = 0.95

USE  $T_p = C_T \times (L')^{0.6}$

$T_p = C_T \times (L')^{0.6} = \underline{1.39}$  (hrs)

$L' = \text{LONGEST WATERCOURSE FROM DIVIDE TO LAKE} = 1.88 \text{ mi}$

Flow at Start of Storm = 1.5 cfs/sq. mile x Subarea D.A. = 9.9 cfs

Computer Data:

QRCSN = -0.05 (5% of peak flow)

RTIOR = 2.0

Remarks: \_\_\_\_\_

C-11

Data for Dam at Outlet of Subarea A2  
(see Sketch on Sheet C-4)

Name of Dam: BRYANT POND

Height: \_\_\_\_\_ (existing)

Spillway Data:	Existing Conditions	Design Conditions
Top of Dam Elevation	<u>1106.7</u>	<u>SEE TEXT</u>
Spillway Crest Elevation	<u>1104.7</u>	_____
Spillway Head Available (ft)	<u>2.0</u>	_____
Type Spillway	<u>BROAD CRESTED Weir</u>	_____
"C" Value - Spillway	<u>2.7</u>	_____
Crest Length - Spillway (ft)	<u>40</u>	_____
<u>Spillway</u> Peak Discharge (cfs)	_____	_____
Auxiliary Spillway Crest Elevation	<u>NONE</u>	_____
Auxiliary Spillway Head Available (ft)	<u>—</u>	_____
Type Auxiliary Spillway	<u>—</u>	_____
"C" Value - Auxiliary Spillway	<u>—</u>	_____
Crest Length - Auxiliary Spillway (ft)	<u>—</u>	_____
<u>Auxiliary Spillway</u> Peak Discharge (cfs)	<u>—</u>	_____
<u>Combined Spillway</u> Discharge (cfs)	<u>305</u>	_____

Spillway Rating Curve: SEE NEXT SHEET

Elevation	Q Spillway (cfs)	Q Auxiliary Spillway (cfs)	Combined (cfs)
<u>1104.7</u>	_____	_____	<u>0</u>
<u>1105.3</u>	_____	_____	<u>25</u>
<u>1106.4</u>	_____	_____	<u>213</u>
<u>1107.4</u>	_____	_____	<u>381</u>
<u>1107.8</u>	_____	_____	<u>580</u>
<u>1109.1</u>	_____	_____	<u>1053</u>
<u>1110.5</u>	_____	_____	<u>1611</u>
<u>1114.7</u>	_____	_____	<u>3699</u>
<u>1117.4</u>	_____	_____	<u>5381</u>
<u>1125.71</u>	_____	_____	<u>11,539</u>

Spillway Rating  
BRYANT POND DAM



ADJUSTED CRITICAL depth

$$Q = \frac{2.7}{3.1} \sqrt{\frac{A^3 g}{T}}$$

d = depth

A = AREA

T = TOP WIDTH

g = 32.18

V = VELOCITY =  $\frac{Q}{A}$

Q = FLOW

1105.17 ≈ 1105.2

- 1104.71 ≈ 1104.7

$$h_v = \text{VELOCITY head} = \frac{V^2}{2g} = \frac{Q^2}{2gA^2}$$

$$\text{Pool} = W.S. + h_v$$

$$W.S. = d + 1104.7$$

W.S.	d	A	T	Q	h <sub>v</sub>	Pool
1104.7	0	0	N/A	0	0	1104.7
1105.2	.5	10	40	251	.09	1105.3
1105.5	.8	22	40	81	.21	1105.7
1106.0	1.3	42	40	213	.40	1106.4
1106.5	1.8	62	40	381	.59	1107.1
1106.7	2.0	70	40	458	.66	1107.4
1107.0	2.3	82	40	580	.78	1107.8
1108.0	3.3	122	40	1,053	1.12	1109.1
1109.0	4.3	162	40	1,611	1.54	1110.5
1110.0	5.3	202	40	2,243	1.92	1111.9
1112.0	7.3	282	40	3,699	2.67	1114.7
1114.0	9.3	362	40	5,381	3.43	1117.4
1120.0	15.3	602	40	11,539	5.71	1125.71

Data for Dam at Outlet of Subarea A2

Name of Dam: BRYANT POND

**Storage Data:**

[illegible]
$$* \text{ELEV0} - \text{ELEV1} \left( \frac{0.01}{A_1} \right) * S_1 = \frac{\text{HEIGHT OF SPILLWAY} \times \text{RESERVOIR AREA}}{3}$$

**\*\* Planimetered contour at least 10 feet above top of dam**

Reservoir Area at Top of Dam is NEGLECTIBLE <sup>UNCONTROLLED</sup> percent of watershed.

Remarks:



Data for Dam at Outlet of Subarea A2

Name of Dam: BRYANT POND

Breach Data:

Sketch of Dam Profile (not to scale):

SEE APPENDIX B  
BREACH AREA - PARTIALLY REPAIRED

Sketch of Top of Dam (not to scale):

SEE APPENDIX B

Soil Type from Visual Inspection: CLAY

Maximum Permissible Velocity (Plate 28, EM 1110-2-1601) 2.5± fps  
(from  $Q = CLH^{3/2} = V \cdot A$  and depth =  $(2/3) \times H$   $A = L \cdot \text{depth}$ )

$$H_{MAX} = (4/9 V^2 / C^2) = \underline{0.29} \text{ ft.}, C = \underline{3.1}$$

$$\underline{0.3} \quad \underline{1106.7}$$

$$H_{MAX} + \text{Top of Dam Elev.} = \underline{1107.0} = \text{FAILEL}$$

(Above is elevation at which failure would start)

Dam Breach Data:

BRWID = 60 ft (width of bottom of breach)

Z = 0 (side slopes of breach)

ELBM = 1093.0 (bottom of breach elevation,  
minimum of zero storage elevation)

WSEL = 1104.7 (normal pool elevation)

T FAIL = 6 mins

= 0.1 hrs (time for breach to develop)

Susquehanna River Basin

Name of Stream: HARVEYS CREEK

Name of Dam: BRYANT POND

NDS ID No.: \_\_\_\_\_

~~DER ID No.~~: \_\_\_\_\_

Latitude: N 41° 19' 00" Longitude: W 76° 04' 15"

Drainage Area: 14.22 sq. mile

Data for Subarea: A2 (see Sketch on Sheet C-4)

Name of Dam at Outlet of Subarea: BRYANT POND

Drainage Area of Subarea: 7.6 sq. mile

Subarea Characteristics:

Assumed Losses: 1.0-inch initial abstraction + 0.05 in/hr

The following are measured from outlet of subarea to the point noted:

L = Length of Main Watercourse extended to the divide = 4.2 mile

LCA = Length of Main Watercourse to the centroid = 1.2 mile

From NAB Data: AREA 12, PLATE F

Cp = 0.30

C<sub>T</sub> = 0.95

Tp = C<sub>T</sub> × (L × L<sub>CA</sub>)<sup>0.3</sup> = 1.54 (hrs)

Flow at Start of Storm = 1.5 cfs/sq. mile × Subarea D.A = 11.4 cfs

Computer Data:

QRCSN = -0.05 (5% of peak flow)

RTIOR = 2.0

Remarks: \_\_\_\_\_

## SELECTED Computer Output

<u>Item</u>	<u>PAGE(S)</u>
MULTI-RATIO ANALYSIS	
INPUT	C-18 TO C-19
SYSTEM PEAK FLOWS	C-20
HARVEYS LAKE DAM	C-21 TO C-22
BRYANT POND DAM	C-23
 DAM BREACH ANALYSIS	
FOR 50% AND 3% PMF *	
INPUT	C-24 TO C-25
SYSTEM PEAK FLOWS	C-26 TO C-27
HARVEYS LAKE DAM	C-28 TO C-29
BRYANT POND DAM	
AND downstream SECTION	C-30
 * NOTE PLAN 1 = NO FAILURE	
PLAN 2 = DAM BREACH	





AD-A078 869


GANNETT FLEMING CORDRY AND CARPENTER INC HARRISBURG PA F/8 13/13  
NATIONAL DAM INSPECTION PROGRAM. BRYANT POND DAM (NDI I.D. NUMB--E+C(U)  
JUL 79 F FUTCHKO DACW31-79-C-0015

UNCLASSIFIED

NL

2 OF 2

AD  
A078869




END

DATE  
FILMED

1-80

DDC



MICROCOPY RESOLUTION TEST CHART  
NATIONAL BUREAU OF STANDARDS-1963-A

C-19

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS  
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)  
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

OPERATION	STATION	AREA	PLAN	RATIOS APPLIED TO FLOWS								
				RATIO 1	RATIO 2	RATIO 3	RATIO 4	RATIO 5	RATIO 6	RATIO 7	RATIO 8	RATIO 9
				1.00	.50	.20	.15	.10	.07	.05	.03	.01
HYDROGRAPH AT	1	6.62	1	12340.	6170.	2468.	1851.	1234.	864.	617.	370.	123.
	(	17.15)	(	340.43)	174.72)	69.89)	52.41)	34.94)	24.46)	17.47)	10.48)	3.79)
ROUTED TO	1	6.62	1	2773.	544.	210.	136.	65.	40.	29.	17.	6.
	(	17.15)	(	78.52)	15.41)	5.95)	3.85)	1.83)	1.14)	.82)	.49)	.16)
ROUTED TO	2	6.62	1	2772.	544.	210.	136.	65.	40.	29.	17.	6.
	(	17.15)	(	78.50)	15.41)	5.95)	3.85)	1.83)	1.14)	.82)	.49)	.16)
ROUTED TO	3	6.62	1	2772.	544.	210.	136.	65.	40.	29.	17.	6.
	(	17.15)	(	78.49)	15.41)	5.95)	3.85)	1.83)	1.14)	.82)	.49)	.16)
ROUTED TO	4	6.62	1	2768.	544.	210.	136.	65.	40.	29.	17.	6.
	(	17.15)	(	78.39)	15.41)	5.95)	3.85)	1.83)	1.14)	.82)	.49)	.16)
ROUTED TO	5	6.62	1	2766.	544.	210.	136.	65.	40.	29.	17.	6.
	(	17.15)	(	78.34)	15.41)	5.94)	3.84)	1.83)	1.14)	.82)	.49)	.16)
HYDROGRAPH AT	5	7.60	1	13276.	6638.	2655.	1991.	1328.	929.	664.	398.	133.
	(	19.68)	(	375.95)	187.97)	75.19)	56.39)	37.59)	26.32)	18.80)	11.28)	3.76)
2 COMBINED	5	14.22	1	13639.	6724.	2678.	2009.	1339.	937.	670.	402.	134.
	(	36.83)	(	386.21)	190.40)	75.84)	56.88)	37.92)	26.54)	18.96)	11.38)	3.79)
ROUTED TO	6	14.22	1	13641.	6722.	2675.	2006.	1330.	923.	647.	372.	116.
	(	36.83)	(	386.26)	190.36)	75.74)	56.80)	37.66)	26.13)	18.32)	10.54)	3.30)



## SUMMARY OF DAM SAFETY ANALYSIS

## HARVEYS LAKE DAM

INITIAL VALUE	SPILLWAY CREST	TOP OF DAM
1255.00	1255.00	1260.80
23856.	23856.	27824.
0.	0.	591.

## PLAN 1 .....

RATIO OF PMF	MAXIMUM RESERVOIR W.S. FLEV	ELEVATION STORAGE OUTFLOW	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
1.00	1263.60		2.80	29880.	2773.	32.50	48.75	0.00
.50	1259.92		0.00	27201.	544.	0.00	52.25	0.00
.20	1257.05		0.00	25228.	210.	0.00	52.50	0.00
.15	1256.57		0.00	24903.	136.	0.00	53.00	0.00
.10	1256.08		0.00	24573.	65.	0.00	54.25	0.00
.07	1255.76		0.00	24360.	40.	0.00	54.75	0.00
.05	1255.54		0.00	24216.	29.	0.00	54.75	0.00
.03	1255.33		0.00	24072.	17.	0.00	54.75	0.00
.01	1255.11		0.00	23928.	6.	0.00	54.75	0.00

## PLAN 1 STATION 2

RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS
1.00	2772.	1255.0	48.75
.50	544.	1252.6	52.50
.20	210.	1251.7	52.50
.15	136.	1251.4	53.25
.10	65.	1251.1	54.50
.07	40.	1250.7	55.00
.05	29.	1250.5	55.00
.03	17.	1250.3	55.00
.01	6.	1250.1	55.00

## PLAN 1 STATION 3

RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS
1.00	2772.	1248.2	49.00
.50	544.	1243.7	52.50
.20	210.	1242.3	52.75
.15	136.	1241.8	53.25
.10	65.	1241.2	54.75
.07	40.	1240.8	55.50
.05	29.	1240.6	55.50
.03	17.	1240.4	55.50
.01	6.	1240.1	55.25

## PLAN 1 STATION 4

RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS
-------	-------------------	-------------------	------------

B

1.00	2768.	1157.7	49.25
.50	544.	1155.2	53.00
.20	210.	1154.4	53.25
.15	136.	1154.0	54.00
.10	65.	1153.5	55.25
.07	40.	1153.3	56.00
.05	29.	1153.2	56.00
.03	17.	1153.1	56.00
.01	6.	1153.0	56.00

PLAN 1 STATION 5

RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS
1.00	2766.	1123.9	49.25
.50	544.	1121.5	53.25
.20	210.	1120.8	53.75
.15	136.	1120.5	54.75
.10	65.	1120.3	56.00
.07	40.	1120.2	56.75
.05	29.	1120.1	56.75
.03	17.	1120.1	56.75
.01	6.	1120.0	56.50

C-22

SUMMARY OF DAM SPILL ANALYSIS

*BRYANT POND DAM*

PLAN 1 .....

RATIO OF PMF	MAXIMUM RESERVOIR W.S.ELEV	ELEVATION STORAGE OUTFLOW	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS	
1.00	1113.02		6.32	257.	13641.	43.75	41.75	0.00	
.50	1111.12		4.42	213.	6722.	41.25	41.75	0.00	
.20	1109.59		2.89	179.	2675.	21.25	41.75	0.00	
.15	1109.24		2.54	172.	2006.	17.00	41.75	0.00	
.10	1108.76		2.06	162.	1330.	12.75	42.00	0.00	
.07	1108.24		1.54	151.	923.	10.25	42.25	0.00	
.05	1107.78		1.04	141.	647.	7.75	42.50	0.00	
.03	1107.04		.34	127.	372.	3.75	43.00	0.00	
.01	1105.84		0.00	104.	116.	0.00	43.25	0.00	

INITIAL VALUE  
1104.70  
83.  
0.

SPILLWAY CREST  
1104.70  
83.  
0.

TOP OF DAM  
1106.70  
120.  
285.

\*\*\*\*\*  
 FLOOD HYDROGRAPH PACKAGE (HEC-1)  
 DAM SAFETY VERSION JULY 1978  
 LAST MODIFICATION 26 FEB 79  
 \*\*\*\*\*

NATIONAL DAM INSPECTION PROGRAM									
HARVEYS CREEK									
BRYANT POND DAM									
1	A1	300	0	6	0	0	0	-4	0
2	A2								
3	A3								
4	R								
5	R1								
6	J	2	1						
7	J1	.03							
8	K	0							
9	K1	1	14.22						
10	M	1	14.22						
11	P	1	114	123					
12	T	1	21.7						
13	V	1.39	.20						
14	X	-1.5	-0.05	2.0					
15	K	1							
16	K1	1							
17	V	1							
18	V1	1							
19	V4	1255	1257	1258	1259	1260	1261	1263	1264
20	V5	0	53	198	422	549	601	649	736
21	SA	0	659	702	1020				
22	SE1146.4		1255	1260	1280				
23	S8	1255							
24	SD1260.8								
25	S1	55	90	160	300	300			
26	SV1260.8	1260.9	1261.7	1261.9	1263.5	1270			
27	S8	10	C	1250	.1	1255	1279		
28	S9	10	0	1250	.1	1255	1279		
29	K	1	2						
30	K1	1							
31	V	1							
32	V1	1							
33	V6	.09	.09	1250	1270	1200	.00833	-1	
34	V7	0	1400	500	1300	650	940	1250	1250
35	V7	1220	1240	1490	1300	1990	1400		
36	K	1	3						
37	K1	1							
38	V	1							
39	V1	1							
40	V6	.09	.09	1240	1260	2850	.0105	-1	
41	V7	0	1400	350	1300	420	490	1240	1240
42	V7	600	1260	750	1300	1090	1400		
43	K	1	4						
44	K1	1							
45	V	1							
46	V1	1							
47	V6	.09	.09	1153	1180	5850	.016	-1	
48	V7	0	1260	400	1180	500	600	1153	1153
49	V7	760	1160	840	1180	1300	1260		
50	K	1	5						



ST	ROUTE	OUTFLOW	HARVEYS LAKE	SECT	5
V1	1		1120	1140	4500
V6	09	07	1120	1140	4500
V7	0	1200	200	280	1140
V7	780	1140	920	1160	1200
K	0	5			1
K1	UNCONTROLLED RUNOFF INTO PRYANT POND				
M	1	7.6	14.22		
P	1	21.7	114	123	133
T	1.54	0.30			1.0
X	-1.5	-0.05	2.0		0.05
K	2	5			
K1	COMBINE INFLOW TO PRYANT POND				
K	1	6			1
K1	ROUTE THROUGH PRYANT POND				
V	1		1		
V1	1		1107.8	1109.1	1110.5
V4	1104.7	1105.3	1106.4	1107.1	1107.8
V5	0	25	213	381	580
SA	0	18	50		
SE	1090.9	1104.7	1120		
SS	1104.7				
SD	1104.7				
SL	1	62	77	118	206
SV	1106.7	1107.9	1108.3	1108.6	1108.7
SB	60	0	1093	1	1104.7
SR	60	0	1093	1	1104.7
K	1	7			1
K1	ROUTE TO DAMAGE CENTER				
V	1		1		
V1	1		1089	1120	2400
V6	09	07	1089	1120	2400
V7	0	1200	550	1140	650
V7	800	1100	1400	1120	1600
K	99				

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS  
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)  
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

OPERATION	STATION	AREA	PLAN	RATIOS APPLIED TO FLOWS	
				RATIO 1	RATIO 2
				.50	.03
HYDROGRAPH AT	1	( 6.62 17.15 )	1	6101.	366.
			2	( 172.77 )	( 10.37 )
ROUTED TO	1	( 6.62 17.15 )	1	526.	16.
			2	( 14.88 )	( .45 )
ROUTED TO	2	( 6.62 17.15 )	1	526.	16.
			2	( 14.88 )	( .45 )
ROUTED TO	3	( 6.62 17.15 )	1	525.	16.
			2	( 14.87 )	( .45 )
ROUTED TO	4	( 6.62 17.15 )	1	525.	16.
			2	( 14.87 )	( .45 )
ROUTED TO	5	( 6.62 17.15 )	1	525.	16.
			2	( 14.87 )	( .45 )
HYDROGRAPH AT	5	( 7.60 19.68 )	1	6616.	397.
			2	( 187.34 )	( 11.24 )
2 COMBINED	5	( 14.22 36.83 )	1	6676.	400.
			2	( 189.05 )	( 11.32 )
ROUTED TO	6	( 14.22 36.83 )	1	6675.	371.
			2	( 189.02 )	( 10.49 )
ROUTED TO	7	( 14.22 36.83 )	1	6672.	369.
			2	( 188.94 )	( 10.45 )

A

0

2 6658 4809  
( 100.55)( 130.16)(

0

SUMMARY OF DAM SAFETY ANALYSIS

HARVEYS LAKE DAM

INITIAL VALUE SPILLWAY CREST TOP OF DAM  
 1255.00 1255.00 1260.80  
 23856. 23856. 27824.  
 0. 0. 591.

ELEVATION  
 STORAGE  
 OUTFLOW

PLAN 1 .....

RATIO OF PMF	MAXIMUM RESERVOIR W.S.ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
.50	1259.60	0.00	26974.	526.	0.00	25.80	0.00
.03	1255.30	0.00	24054.	16.	0.00	26.90	0.00

INITIAL VALUE SPILLWAY CREST TOP OF DAM  
 1255.00 1255.00 1260.80  
 23856. 23856. 27824.  
 0. 0. 591.

ELEVATION  
 STORAGE  
 OUTFLOW

PLAN 2 .....

RATIO OF PMF	MAXIMUM RESERVOIR W.S.ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
.50	1259.60	0.00	26974.	526.	0.00	25.80	0.00
.03	1255.30	0.00	24054.	16.	0.00	26.90	0.00

PLAN 1 STATION 2

RATIO	MAXIMUM FLOW,CFS	MAXIMUM STAGE,FT	TIME HOURS
.50	526.	1252.5	25.90
.03	16.	1250.3	27.20

PLAN 2 STATION 2

RATIO	MAXIMUM FLOW,CFS	MAXIMUM STAGE,FT	TIME HOURS
.50	526.	1252.5	25.90
.03	16.	1250.3	27.20

PLAN 1 STATION 3

RATIO	MAXIMUM FLOW,CFS	MAXIMUM STAGE,FT	TIME HOURS
.50	525.	1243.7	26.10
.03	16.	1240.3	27.60

PLAN 2 STATION 3



RATIO	MAXIMUM FLOW,CFS	MAXIMUM STAGE,FT	TIME HOURS
.50	525.	1243.7	26.10
.03	16.	1240.3	27.00

PLAN 1 STATION 4

RATIO	MAXIMUM FLOW,CFS	MAXIMUM STAGE,FT	TIME HOURS
.50	525.	1155.1	26.60
.03	16.	1153.1	28.40

PLAN 2 STATION 4

RATIO	MAXIMUM FLOW,CFS	MAXIMUM STAGE,FT	TIME HOURS
.50	525.	1155.1	26.60
.03	16.	1153.1	28.40

PLAN 1 STATION 5

RATIO	MAXIMUM FLOW,CFS	MAXIMUM STAGE,FT	TIME HOURS
.50	525.	1121.5	26.90
.03	16.	1120.1	29.00

PLAN 2 STATION 5

RATIO	MAXIMUM FLOW,CFS	MAXIMUM STAGE,FT	TIME HOURS
.50	525.	1121.5	26.90
.03	16.	1120.1	29.00

SUMMARY OF DAM SAFETY ANALYSIS

*BRYANT POND DAM*

PLAN 1 .....

RATIO OF PMF	ELEVATION STORAGE OUTFLOW	MAXIMUM RESERVOIR W.S.ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
.50	1111.11	4.41	213.	6675.	17.70	17.60	0.00	0.00
.03	1107.04	.34	127.	371.	3.60	18.90	0.00	0.00

INITIAL VALUE	SPILLWAY CREST	TOP OF DAM
1104.70	1104.70	1106.70
8% 0.	83. 0.	120. 285.

PLAN 2 .....

RATIO OF PMF	ELEVATION STORAGE OUTFLOW	MAXIMUM RESERVOIR W.S.ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
.50	1107.03	.33	127.	8359.	.65	13.00	12.90	12.90
.03	1107.00	.30	126.	8244.	1.15	18.40	18.30	18.30

INITIAL VALUE	SPILLWAY CREST	TOP OF DAM
1104.70	1104.70	1106.70
8% 0.	83. 0.	120. 285.

GANNETT FLEMING CORDDRY  
AND CARPENTER, INC.  
HARRISBURG, PA.

SUBJECT \_\_\_\_\_ FILE NO. \_\_\_\_\_  
SHEET NO. \_\_\_\_\_ OF \_\_\_\_\_ SHEETS  
FOR \_\_\_\_\_  
COMPUTED BY \_\_\_\_\_ DATE \_\_\_\_\_ CHECKED BY \_\_\_\_\_ DATE \_\_\_\_\_

## TABLE OF PERTINENT RESULTS

PMF RAINFALL = 25.02"		
	PMF	1/2 PMF
RUNOFF (INCHES - APPROXIMATE)	22.4	11.2
HARVEYS LAKE DAM		
INFLOW - CFS	12,340	6,170
OUTFLOW - CFS	2,773	544
BRYANT POND DAM		
INFLOW - CFS	13,639	6,724
OUTFLOW - CFS	13,641	6,722
DEPTH OF OVERTOPPING (FT)	6.32	4.42
DURATION OF OVERTOPPING (HRS)	43.75	41.25

## BREACH DATA

BREACH RESULTS IN PEAK OUTFLOW OF  
8300 CFS± IN EACH CASE

WATER SURFACE ELEV

AT DOWNSTREAM SECTION

	<u>NO FAILURE</u>	<u>DAM BREACH</u>
50% PMF	1101.7	1101.7
3% PMF	1091.8	1100.1






NOTE:

NUMBERS INDICATE STATIONS  
USED IN COMPUTER ANALYSIS.

2000

SCALE:





PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM

BRYANT POND DAM

ESTATE OF GLENDORA BRYANT

STREAM CROSS SECTIONS

JULY 1979

PLATE C-1

TE STATIONS  
ANALYSIS.

2000 0 2000

SCALE: 1 IN. = 2000 FT.

SUSQUEHANNA RIVER BASIN  
HARVEYS CREEK, LUZERNE COUNTY  
PENNSYLVANIA

BRYANT POND DAM

NDI ID No. PA-00544  
DER ID No. 40-11


ESTATE OF GLENDORA BRYANT

PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM

JULY 1979

APPENDIX D  
PHOTOGRAPHS

BRYANT POND DAM




A. Top of Dam



B. Upstream Slope



BRYANT POND DAM



C. Downstream Slope and Seepage



D. Washout Near Ice Chute



BRYANT POND DAM



E. Breach Area



F. Breach Area

BRYANT POND DAM



G. Spillway



H. Spillway

BRYANT POND DAM



I. Outlet Works



J. Harveys Lake Dam -  
Upstream From Bryant Pond Dam



SUSQUEHANNA RIVER BASIN  
HARVEYS CREEK, LUZERNE COUNTY  
PENNSYLVANIA

BRYANT POND DAM

NDI ID No. PA-00544  
DER ID No. 40-11

ESTATE OF GLENDORA BRYANT  
PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM

JULY 1979

APPENDIX E

GEOLOGY



## BRYANT POND DAM

### APPENDIX E

#### GEOLOGY

1. General Geology. The damsite and reservoir are located in Luzerne County. The rock formations exposed in Luzerne County range from the Post-Pottsville formations, of Pennsylvanian Age, down to the Onondaga formation, of Middle Devonian Age. The Wisconsin terminal moraine crosses the southern part of the County, and the greater part of the County is covered by glacial drift. Extensive deposits of glacial outwash occur along the Susquehanna River and less extensive deposits along the smaller streams.

Nearly all of Luzerne County lies in the Valley and Ridge Province in which nearly all the rocks have been strongly folded. In going from north to south across the County, five major folds are encountered, all of which trend northeast. The first of these is a shallow syncline on the crest of North Mountain, forming the Mehoopnay coal basin. The second is the Milton Anticline, which exposes the Portage group in the northwestern part of the County and gradually flattens out toward the northeast. The third and most pronounced is the Lackawanna Syncline, which originates in Lackawanna County to the north, and has preserved the post-Pottsville formations throughout the Wyoming Valley. The maximum depth of this syncline is reached in the vicinity of Wilkes-Barre and Plymouth. The double rim of this syncline is formed by the resistant Pottsville formation and Pocono sandstone, separated by the less resistant Mauch Chunk shale. The fourth fold is the Berwick (Montour) Anticline, which exposes a few feet of the Onondaga formation in the vicinity of Beach Haven. This fold reaches its maximum development farther west and only the eastern portion reaches Luzerne County. The fifth major fold comprises a series of anticlines and synclines forming the Eastern Middle Anthracite Field in the vicinity of Hazleton. The synclinal basins in this region are relatively shallow and there are large areas from which all coalbeds have been eroded.

The general dips of the region vary from 0° to 40°, and the maximum dips are found on the rims and within the synclinal coal basins. The relatively soft Post-Pottsville beds in their cores are severely folded and contorted with numerous minor faults. The northern and easternmost parts of the County border the Appalachian Plateau Province and are characterized by horizontal, or nearly horizontal strata. The Catskill continental group of rocks underlies those parts of Luzerne County that are outside of the five major folds.

2. Site Geology. Bryant Pond Dam is situated on an "uncertain foundation" of the Catskill formation of late Devonian Age. The Catskill formation is composed of red shale, red and gray crossbedded sandstone, white sandstone, and gray shale and sandstone. This formation underlies the county and crops out north and south of the Wyoming Valley. Crossbedding, channeling, and cut-and-fill features are common to the sandstone and conglomerate units. Bedding is usually well developed with thicknesses ranging from less than one foot to 10 to 16 feet in the coarser beds. Shales of this formation tend to air-slake. Sandstones and conglomerates are moderately resistant to weathering.

Information concerning the actual foundation conditions is scant. The original owner reported to the Pennsylvania Water Supply Commission that the concrete core-wall was founded on either "rock or hardpan".



